s Form 10-900-a <sup>(2)</sup> <b>nited States Department of the Interior</b>		OMB NO. Expires	1024-0018
nited States Department of the Interior		Expires	10-31-87
		111	a series a
ational Park Service	For NP	S use only	
<b>lational Register of Historic Places</b>	receiv	ed SEP 1	c 1000
nventory-Nomination Form	date e	ntered	0 1900
iventory-itoinination ronni			
ontinuation sheet Cuero, Texas M-R Nomination Item number all		Page 1	.2
TEXAS HISTORIC SITES INVENTORY FORM - TEXAS HISTORICAL	COMMISSION	(rev 8-82)	
. County DEWITT DEW 5. USGS Quad No. 2997-		Site No	259
City/Rural_CUERD CU UTM Sector_666-3219	)		1.00
Name PRIGDEN, D.F. & MARY, HOUSE 6. Date: Factual 1913		Est.	12-11-12
Address 401 E FRENCH 7. Architect/Builder Unkn	IOWN		
	Contractor		
Owner Rerett & Freda Bruns 8. Style/Type Bungalow	1.4.2		
Address Rte 2, Box 202 Goliad TX 77963 9. Original Use reside			and the los
Block/Lot OTS/Blk 109/Lots 1,2 Present Use reside	And in case of the local division of the loc		
Description 1-story frame dwelling w/ bungalow plan; exterior			1-
aidians ashis and ut anaraihing shirelans shirk basel	abor would a		
siding; gable roof w/ composition shingles; stick brack			
hung windows w/ 1/1 lights; single-door primary entranc	e w/ transc	om; 3-bay	1
hung windows w/ 1/1 lights; single-door primary entranc porch w/ gable roof that is L shaped on N. and W. elev.	e w/ transc	om; 3-bay	1
hung windows w/ 1/1 lights; single-door primary entranc porch w/ gable roof that is L shaped on N. and W. elev. Present Condition good	e w/ transc ; tapered t	om; 3-bay box colum	ns
hung windows w/ 1/1 lights; single-door primary entranc porch w/ gable roof that is L shaped on N. and W. elev. Present Condition good Significance ARCHITECTURE: This frame structure, built for	e w/ transc ; tapered t O.F. and Ma	om; 3-bay box colum ary Prigd	en,
hung windows w/ 1/1 lights; single-door primary entranc porch w/ gable roof that is L shaped on N. and W. elev. Present Condition good Significance ARCHITECTURE: This frame structure, built for is one of Cuero's premier examples of bungalow architec	e w/ transo ; tapered t O.F. and Ma ture. The	om; 3-bay box colum ary Prigd heavy cr	en, 055-
hung windows w/ 1/1 lights; single-door primary entranc porch w/ gable roof that is L shaped on N. and W. elev. Present Condition good Significance ARCHITECTURE: This frame structure, built for is one of Cuero's premier examples of bungalow architec gable roof, tapered box columns and brackets are notewo	e w/ transo ; tapered t 0.F. and Ma ture. The rthy. The	om; 3-bay oox colum ary Prigd heavy cr Prigdens	en, 1055-
hung windows w/ 1/1 lights; single-door primary entranc porch w/ gable roof that is L shaped on N. and W. elev. Present Condition good Significance ARCHITECTURE: This frame structure, built for is one of Cuero's premier examples of bungalow architec gable roof, tapered box columns and brackets are notewo Relationship to Site: Moved Date or Original Site *(describ	D.F. and Ma ture. The rthy. The in a res	om; 3-bay box colum ary Prigd heavy cr Prigdens sidential	en, 055- area
hung windows w/ 1/1 lights; single-door primary entranc porch w/ gable roof that is L shaped on N. and W. elev. Present Condition good Significance ARCHITECTURE: This frame structure, built for is one of Cuero's premier examples of bungalow architec gable roof, tapered box columns and brackets are notewo Relationship to Site: Moved Date or Original Site *(describ northeast of the CBD; at the southeast corner of French	D.F. and Ma ture. The rthy. The in a res	om; 3-bay box colum ary Prigd heavy cr Prigdens sidential	en, 055- area
hung windows w/ 1/1 lights; single-door primary entranc porch w/ gable roof that is L shaped on N. and W. elev. Present Condition good Significance ARCHITECTURE: This frame structure, built for is one of Cuero's premier examples of bungalow architec gable roof, tapered box columns and brackets are notewo Relationship to Site: Moved Date or Original Site X (describ northeast of the CBD; at the southeast corner of French Bibliography Tax Rolls, Sanborn Maps 15. Informant	D.F. and Ma ture. The rthy. The in a res	om; 3-bay box colum ary Prigd heavy cr Prigdens sidential d streets	en, 055- area
hung windows w/ 1/1 lights; single-door primary entrance         porch w/ gable roof that is L shaped on N. and W. elev.         Present Condition good         Significance ARCHITECTURE: This frame structure, built for         is one of Cuero's premier examples of bungalow architec         gable roof, tapered box columns and brackets are notewo         Relationship to Site: Moved Date or Original Site *(describe         northeast of the CBD; at the southeast corner of French         Bibliography Tax Rolls, Sanborn Maps       15. Informant         Mechanic's Liens Vol. 2, pg. 226       16. Recorder Hardy-He	e w/ transo ; tapered to 0.F. and Ma ture. The rthy. The oe) in a res and McLeoo ck-Moore	om; 3-bay box colum ary Prigd heavy cr Prigdens sidential d streets Date J	en, 055- area
hung windows w/ 1/1 lights; single-door primary entranc porch w/ gable roof that is L shaped on N. and W. elev. Present Condition good Significance ARCHITECTURE: This frame structure, built for is one of Cuero's premier examples of bungalow architec gable roof, tapered box columns and brackets are notewo Relationship to Site: Moved Date or Original Site X (describ northeast of the CBD; at the southeast corner of French Bibliography Tax Rolls, Sanborn Maps 15. Informant	e w/ transo ; tapered to 0.F. and Ma ture. The rthy. The oe) in a res and McLeoo	om; 3-bay box colum ary Prigd heavy cr Prigdens sidential d streets Date J	en, 055- area
hung windows w/ 1/1 lights; single-door primary entranc porch w/ gable roof that is L shaped on N. and W. elev. Present Condition good Significance ARCHITECTURE: This frame structure, built for is one of Cuero's premier examples of bungalow architec gable roof, tapered box columns and brackets are notewo Relationship to Site: Moved Date or Original Site X (describe northeast of the CBD; at the southeast corner of French Bibliography Tax Rolls, Sanborn Maps 15. Informant Mechanic's Liens Vol. 2, pg. 226 16. Recorder Hardy-He DESIGNATIONS -	e w/ transo ; tapered to 0.F. and Ma ture. The rthy. The pe) in a res and McLeoo ck-Moore PHOTO DATA	om; 3-bay box colum ary Prigd heavy cr Prigdens sidential d streets Date J	en, 055- area
hung windows w/ 1/1 lights; single-door primary entrance         porch w/ gable roof that is L shaped on N. and W. elev.         Present Condition good         Significance ARCHITECTURE: This frame structure, built for         is one of Cuero's premier examples of bungalow architec         gable roof, tapered box columns and brackets are notewo         Relationship to Site: Moved Date or Original Site *(describe         northeast of the CBD; at the southeast corner of French         Bibliography Tax Rolls, Sanborn Maps       15. Informant         Mechanic's Liens Vol. 2, pg. 226       16. Recorder Hardy-He         DESIGNATIONS       -         IS No.       Old THC Code       B&W 4×5s         IRTHL       HABS (no.)       TEX       35mm Negs	e w/ transo ; tapered to 0.F. and Ma ture. The rthy. The rthy. The one in a res and McLeoo ck-Moore PHOTO DATA S	box colum ary Prigd heavy cr Prigdens sidential d streets Date J	uly 198
hung windows w/ 1/1 lights; single-door primary entrance         porch w/ gable roof that is L shaped on N. and W. elev.         Present Condition good         Significance ARCHITECTURE: This frame structure, built for         is one of Cuero's premier examples of bungalow architec         gable roof, tapered box columns and brackets are notewo         Relationship to Site: Moved Date or Original Site *(describe         northeast of the CBD; at the southeast corner of French         Bibliography Tax Rolls, Sanborn Maps       15. Informant         Mechanic's Liens Vol. 2, pg. 226       16. Recorder Hardy-He         DESIGNATIONS       -         IS No.       Old THC Code       B&W 4×5s         RTHL       HABS (no.) TEX       35mm Negs         Individual       Historic District       YEAR DRWR R	e w/ transo ; tapered to 0.F. and Ma ture. The rthy. The pe) in a res and McLeoo ck-Moore PHOTO DATA S OLL FRME	box colum ary Prigd heavy cr Prigdens sidential d streets Date J	en, 055- area
hung windows w/ 1/1 lights; single-door primary entrance         porch w/ gable roof that is L shaped on N. and W. elev.         Present Condition	e w/ transo ; tapered t 0.F. and Ma ture. The rthy. The pe) in a res and McLeod ck-Moore PHOTO DATA S OLL FRME 0 28	box colum ary Prigd heavy cr Prigdens sidential d streets Date Uides to	uly 198
hung windows w/ 1/1 lights; single-door primary entrance         porch w/ gable roof that is L shaped on N. and W. elev.         Present Condition good         Significance ARCHITECTURE: This frame structure, built for         is one of Cuero's premier examples of bungalow architec         gable roof, tapered box columns and brackets are notewo         Relationship to Site: Moved Date or Original Site *(describe         northeast of the CBD; at the southeast corner of French         Bibliography Tax Rolls, Sanborn Maps       15. Informant         Mechanic's Liens Vol. 2, pg. 226       16. Recorder Hardy-He         DESIGNATIONS       -         IS No.       Old THC Code       B&W 4×5s         RTHL       HABS (no.) TEX       35mm Negs         Methanicidual       Historic District       YEAR DRWR R	e w/ transo ; tapered t 0.F. and Ma ture. The rthy. The pe) in a res and McLeod ck-Moore PHOTO DATA S OLL FRME 0 28	box colum ary Prigd heavy cr Prigdens sidential d streets Date lides4 to to	uly 198
hung windows w/ 1/1 lights; single-door primary entrance         porch w/ gable roof that is L shaped on N. and W. elev.         Present Condition	e w/ transo ; tapered t 0.F. and Ma ture. The rthy. The pe) in a res and McLeod ck-Moore PHOTO DATA S OLL FRME 0 28	box colum ary Prigd heavy cr Prigdens sidential d streets Date Uides to	uly 198
hung windows w/ 1/1 lights; single-door primary entranc         porch w/ gable roof that is L shaped on N. and W. elev.         Present Condition good         Significance ARCHITECTURE: This frame structure, built for         is one of Cuero's premier examples of bungalow architec         gable roof, tapered box columns and brackets are notewo         Relationship to Site: Moved Date or Original Site X(describe         northeast of the CBD; at the southeast corner of French         Bibliography Tax Rolls, Sanborn Maps 15. Informant         Mechanic's Liens Vol. 2, pg. 226       16. Recorder         IS NoOld THC Code       B&W 4×5s         IS NoOld THC Code       B&W 4×5s         IS NoOld THC Code       B&W 4×5s         IN Individual       Historic District       35mm Negs YEAR DRWR R         IN File Name	e w/ transo ; tapered t 0.F. and Ma ture. The rthy. The pe) in a res and McLeod ck-Moore PHOTO DATA S OLL FRME 0 28	bary Prigd heavy cr Prigdens sidential d streets Date _J Hides _4 RC to to to	28
hung windows w/ 1/1 lights; single-door primary entranc         porch w/ gable roof that is L shaped on N. and W. elev.         Present Condition	e w/ transo ; tapered t 0.F. and Ma ture. The rthy. The pe) in a res and McLeod ck-Moore PHOTO DATA S OLL FRME 0 28	bary Prigd heavy cr Prigdens sidential d streets Date _J Hides _4 RC to to to	uly 198
hung windows w/ 1/1 lights; single-door primary entranc         porch w/ gable roof that is L shaped on N. and W. elev.         Present Condition good         Significance ARCHITECTURE: This frame structure, built for         is one of Cuero's premier examples of bungalow architec         gable roof, tapered box columns and brackets are notewo         Relationship to Site: Moved Date or Original Site *(describe         northeast of the CBD; at the southeast corner of French         Bibliography Tax Rolls, Sanborn Maps       15. Informant         Mechanic's Liens Vol. 2, pg. 226       16. Recorder Hardy-He         DESIGNATIONS       -         IS No.       Old THC Code       B&W 4×5s         Is Individual       Historic District       YEAR DRWR R         Individual       Historic District       YEAR DRWR R         NR File Name       5         Market Name       5	e w/ transo ; tapered t 0.F. and Ma ture. The rthy. The pe) in a res and McLeod ck-Moore PHOTO DATA S OLL FRME 0 28 4 25	bay 3-bay box colum ary Prigd heavy cr Prigdens sidential distrects Date Date Hides to to to to to No	28
hung windows w/ 1/1 lights; single-door primary entranc         porch w/ gable roof that is L shaped on N. and W. elev.         Present Condition good         Significance ARCHITECTURE: This frame structure, built for         is one of Cuero's premier examples of bungalow architec         gable roof, tapered box columns and brackets are notewo         Relationship to Site: Moved Date or Original Site X(describe         northeast of the CBD; at the southeast corner of French         Bibliography Tax Rolls, Sanborn Maps 15. Informant         Mechanic's Liens Vol. 2, pg. 226       16. Recorder         IS NoOld THC Code       B&W 4×5s         IS NoOld THC Code       B&W 4×5s         IS NoOld THC Code       B&W 4×5s         IN Individual       Historic District       35mm Negs YEAR DRWR R         IN File Name	e w/ transo ; tapered t 0.F. and Ma ture. The rthy. The pe) in a res and McLeod ck-Moore PHOTO DATA S OLL FRME 0 28 4 25	bay 3-bay box colum ary Prigd heavy cr Prigdens sidential distrects Date Date Hides to to to to to No	28
hung windows w/ 1/1 lights; single-door primary entranc         porch w/ qable roof that is L shaped on N. and W. elev.         Present Condition good         SignificanceARCHITECTURE: This frame structure, built for         is one of Cuero's premier examples of bungalow architec         qable roof, tapered box columns and brackets are notewo         Relationship to Site: Moved or Original Site (describe	e w/ transo ; tapered t 0.F. and Ma ture. The rthy. The pe) in a res and McLeod ck-Moore PHOTO DATA S OLL FRME 0 28 4 25 COMMISSION	bary Prigd heavy cr Prigdens sidential d streets Date Uides to to to No (rev.8-82)	2
hung windows w/ 1/1 lights; single-door primary entranc         porch w/ gable roof that is L shaped on N. and W. elev.         Present Condition	e w/ transo i tapered to 0.F. and Ma ture. The rthy. The pe) in a res and McLeod ck-Moore PHOTO DATA S OLL FRME 0 28 4 25 COMMISSION 121	bay 3-bay box colum ary Prigd heavy cr Prigdens sidential distrects Date J Hides 4 RC to 54 to 54 to 54	2
hung windows w/ 1/1 lights; single-door primary entranc         porch w/ gable roof that is L shaped on N. and W. elev.         Present Conditiongood         SignificanceARCHITECTURE: This frame structure, built for is one of Cuero's premier examples of bungalow architec gable roof, tapered box columns and brackets are notewo         Relationship to Site: MovedDate or Original SiteX(describ northeast of the CBD; at the southeast corner of French         BibliographyTax Rolls, Sanborn Maps 15. Informant	e w/ transo ; tapered to 0.F. and Ma ture. The rthy. The pe) in a res and McLeoo ck-Moore PHOTO DATA S OLL FRME 0 28 4 25 COMMISSION 121 /3219300	bary Prigd heavy cr Prigdens sidential d streets Date Uides to to to No (rev.8-82)	2

Significance continued: sold the house to Charles Breeden in 1917, who sold it to Louis Schorre in 1924.

4

40

United States Department of the Interior National Park Service

## National Register of Historic Places Continuation Sheet

	Multiple Resource Area Thematic Group
Name Cuero MRA	
State DeWitt County, TEXAS	
Nomination/Type of Review	Date/Signature
41. Old Beer and Ice Warehouse Entered in Stional Re	ine fikeeper Allung Syen 10/3/0
	Attest
42. Ott, Charles J. and Alvina, House Substantive Review	
	Attest
43. Ott, S.I., House Entered in the National Regist	fikeeper Allous gur 18/31/8
44. Prigden, O.F. and Mary, House	Keeper Carald Sheel 10-31-
Substantive Neview	Attest
45. Reuss, J.M., House Entered in the National Tagister	fikeeper Delour Byen 10/3
	Attest
6. St. Michael's Catholic Church	Keeper Caracoohull 10-31-
Substantive Review	Attest
7. Stevens, Elisha, House Intered in the National Begis	Keeper Aclouer 10/3
	Attest
8. Terrell-Reuss Streets Historic District	Keeper Beth Boland 11/4/88
Substantive Review	Attest
9. Thomson, W.F., House Entered in the National Degister	Keeper Alloustyen 10/31/8
1801000 mg	Attest
50. Wittenbert, Dane, House	Keeper Belf Boland 10/31/88
Substentiva Baylaw	Attest

#### UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES EVALUATION/RETURN SHEET

REQUESTED ACTION: NOMINATION

PROPERTY Prigden, O. F. and Mary, House NAME:

MULTIPLE Cuero MRA NAME:

STATE & COUNTY: TEXAS, De Witt

DATE RECEIVED: 9/16/88 DATE OF PENDING LIST: 9/27/88 DATE OF 16TH DAY: 10/13/88 DATE OF 45TH DAY: 10/31/88 DATE OF WEEKLY LIST:

REFERENCE NUMBER: 88001958

NOMINATOR: STATE

REASONS FOR REVIEW:

APPEAL: N DATA PROBLEM: N LANDSCAPE: N LESS THAN 50 YEARS: N OTHER: N PDIL: N PERIOD: N PROGRAM UNAPPROVED: N REQUEST: N SAMPLE: Y SLR DRAFT: N

COMMENT WAIVER: N

ACCEPT

ABSTRACT/SUMMARY COMMENTS:

One of the premier local examples of the Bungalow design style.

RECOM./CRITH	ERIA Accept-C
REVIEWER	Noble
DISCIPLINE	Historian
DATE /0/3/	/88

DOCUMENTATION see attached comments Y/N see attached SLR Y/N

### CLASSIFICATION

count resource type

STATE/FEDERAL AGENCY CERTIFICATION

FUNCTION

historic current

DESCRIPTION

architectural classification materials descriptive text

#### SIGNIFICANCE

Period Areas of Significance--Check and justify below

Specific dates Builder/Architect Statement of Significance (in one paragraph)

summary paragraph	
completeness	
clarity	
applicable criteria	
justification of areas checked	
relating significance to the resource	
relationship of integrity to significance justification of exception	

other

BIBLIOGRAPHY		
GEOGRAPHICAL DATA		
acreageverbal boundary UTMsboundary justif		
ACCOMPANYING DOCUMENTATION/PRESENT	ATION	
sketch mapsUSGS maps	photographs _	presentation
OTHER COMMENTS		j.
Questions concerning this nominati	on may be dire	cted to
	Phone	VINAN
Signed	Da	te



"Historic Resources of Cuero, Texas" Multiple-Resource Nomination; city limits of Cuero, DeWitt County, Texas. Photo: David Moore of Hardy-Heck-Moore, Inc. 1986; negative with Texas Historical Commission, Austin, Texas. Subject: O.F. & Mary Prigden House, Site No. 259 401 E. French View: Camera looking southeast Photo 12 of 77

# Please refer to the map in the Multiple Property Cover Sheet for this property

Multiple Property Cover Sheet Reference Number: 64000839