

United States Department of the Interior National Park Service

National Register of Historic Places Inventory—Nomination Form

For NPS use only received JUL | 4 1983 date entered

Continuation sheet

Item number A11

Page 24

11. Name: Cemetery Chapel,

TX12

Location: San Marcos Cemetery, on State Highway 12, northwest of central San Marcos.

Classification: Category - structure; Ownership - public; Status - unoccupied;

Accessible - yes, unrestricted; Present use - religious.

Oner of property: City of San Marcos

Dr. Emmie Craddock, Mayor

City Hall

San Marcos, Texas 78666

Description: Condition - good; Altered; Original site

More a pavilion than a building, the Cemetery Chapel is a white, cruciform, frame structure, the arms of which practically consist of large, straight-sided, pointed arches. Dimensions of the two axes are 46'6" x 16'6", and 36'6" x 16'6". The "walls" are one bay in width, except for the nave, which contains two bays. Four gables are covered in corrugated metal.

The Chapel's construction is of single boards with exterior battens on a frame of heavy square posts. Rough logs fastened with iron spikes form the foundation. There is no ceiling; the truss system is visible and creates an attractive pattern against the roof boards.

Wooden benches are affixed to the transept arches on both sides. Originally, there were freestanding benches also, but these have been removed. The floor is unpaved. A gutter and cistern system for collecting rainwater were replaced by a well, windmill, and wooden tank, but these fell into disrepair. Their removal did not damage the chapel.

A major attribute of the chapel is the peaceful setting, on a hill overlooking the cemetery on one side and distant blue hills on the other.

Significance: Period - 1890-1899; Areas of significance - architecture.

Specific dates - 1866. Edward Northcraft, architect; Ralph Smith, builder

American Gothic Revival tastes ran the gamut from frilly to stark. San Marcos' Cemetery Chapel is in the latter category, "Carpenter Gothic". The open air plan also recalls the brush arbors that served the first pioneers until they could afford genuine sanctuaries.

United States Department of the Interior National Park Service

National Register of Historic Places Inventory—Nomination Form

For NPS use only received JUL 1 4 1981 date entered

Continuation sheet

Item number A11

Page 25

The earliest settlers used a plot in the Lindsey addition, a block from where the First Methodist Church now stands, as a cemetery. Mrs. W.W. Moon was the first person buried there, in 1846. The City of San Marcos Cemetery Association in 1876 bought a plot further from the town where a few people, including six slaves, had already been interred. This became the present cemetery.

Before the chapel was built, mourners had to make a long carriage journey into town for the service and then another out to the cemetery. This was too time consuming for those who wanted to be back on the farm by dark. Also, cemetery chapels were "in vogue" across the southwest where mild weather made them possible. So architect Edward Northcraft and builder Ralph Smith were contracted in 1886 to erect a chapel on a cross plan. They would have five months to complete the \$450 structure. Their work was well received. The chapel has hosted the last rites of the town's most respected citizens and veterans of the Civil, Spanish-American, and World Wars.

Bibliography:

Recorded Texas Historic Marker file, Texas Historical Commission, Austin, Texas.

<u>Historical Markers in Hays County</u> (see general bibliography for full listing),
p. 150.

The Free Press, January 7, 1886.

Speech by Tula Townsend Wyatt, November 11, 1966, recorded by the Hays County Historical and Genealogical Society, on file at the San Marcos Public Library.

Geographical data: Acreage - less than one acre
UTM reference - 14 / 600690 / 3306500

Verbal Boundary Description - The chapel is located 400 ft. south of the southern-most extension of the 800 ft. contour line of a scarp that straddles State Highway 12. (The eastern 800 ft. line crosses Highway 12 about 400 ft. northwest of the city limit). The chapel's boundaries are shaped like a lozenge, the points of which are 35 ft. from the midpoints of the cruciform structure's end walls. The sides of the lozenge are, therfore, at 45° angles from the chapel walls and face (approximately) the cardinal directions. The structure and immediate environs are included.

WASO Form - 177 ("R" June 1984)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE


NATIONAL REGISTER OF HISTORIC PLACES EVALUATION/RETURN SHEET

Cemetery Chapel, San Marcos Ce	metery (San					
Marcos MRA)						
Hays County			nulah			
TEXAS			Working No. <u>7-14-83</u>			
			Fed. Reg. Date: Date Due: 8/11/83-8	1/28/83		
			A-MI ACCEPT			
resubmission			Action:ACCEPT	8/26/83		
nomination by person or local government			REJECT			
owner objection			Federal Agency:			
appeal			Todoral Agency:			
	_	_				
	request	appeal	☐ NR decision			
Reviewer's comments:						
			Recom./Criteria			
			Reviewer			
			Discipline			
			Date			
			see continuation sheet			
			see continuation sheet			
Nomination returned for: technical correc		,				
1. Name						
2. Location						
3. Classification						
Category Ownership Public Acquisition	1	Status Accessible	Present Use			
4. Owner of Property						
5. Location of Legal Description						
6. Representation in Existing Surveys						
Has this property been determined eligible?	☐ yes ☐ r	no				
7. Description						
Condition	Check on	e	Check one			
excellent deteriorated	unalt	ered	original site			
good ruins	altere	ed	moved date			
fair unexposed						
Describe the present and original (if known) physical appearance						
Daymony parament						
summary paragraph						
completeness						
clarity						
alterations/integrity						
dates						
boundary selection						

8. Signific	cance	
Period	Areas of Significance—Check and justify below	
Specific d	lates Builder/Architect t of Significance (in one paragraph)	
Statemen	t of Significance (in one paragraph)	
summ	ary paragraph	Semetery Chapal, San Hargos Cometary (san walls and san a sa
comp		Hays Court
Clarity		
	able criteria cation of areas checked	
	ng significance to the resource	
conte		
	onship of integrity to significance	
	cation of exception	
other		
	THE RESERVE OF THE PARTY OF THE	
9. Major	Bibliographical References	
10. Geog	graphical Data	
Acreage of	of nominated property	
	le name	
UTM Ref	erences	
Verbal bo	oundary description and justification	
11. Forn	n Prepared By	
	Historic Preservation Officer Certification	and the second of the second o
The evalu	uated significance of this property within the state is:	
	nationalstatelocal	
State His	toric Preservation Officer signature	
title	date	and the second s
13. Othe	er	
Mane	Parat On I.	ne uses map
Photo	Property Ovention not marked &	a managamus sa tanan sa kamada ak aliga sa karan sa kara
☐ Other		
Question	s concerning this nomination may be directed to	The second secon
	Selvies Byer Date	\$/26/83 Phone 202-343-9553
Signed (Xulous yes Date	8/26/83 Phone: 202-343-4553

United States Department of the Interior National Park Service

National Register of Historic Places Inventory—Nomination Form



Continuation sheet

Item number A11

Page 24

11. Name: Cemetery Chapel,

TX12

Location: San Marcos Cemetery, on State Highway 12, northwest of central San Marcos.

Classification: Category - structure; Ownership - public; Status - unoccupied;

Accessible - yes, unrestricted; Present use - religious.

Oner of property: City of San Marcos

Dr. Emmie Craddock, Mayor

City Hall

San Marcos, Texas 78666

Description: Condition - good; Altered; Original site

More a pavilion than a building, the Cemetery Chapel is a white, cruciform, frame structure, the arms of which practically consist of large, straight-sided, pointed arches. Dimensions of the two axes are 46'6'' x 16'6'', and 36'6'' x 16'6''. The "walls" are one bay in width, except for the nave, which contains two bays. Four gables are covered in corrugated metal.

The Chapel's construction is of single boards with exterior battens on a frame of heavy square posts. Rough logs fastened with iron spikes form the foundation. There is no ceiling; the truss system is visible and creates an attractive pattern against the roof boards.

Wooden benches are affixed to the transept arches on both sides. Originally, there were freestanding benches also, but these have been removed. The floor is unpaved. A gutter and cistern system for collecting rainwater were replaced by a well, windmill, and wooden tank, but these fell into disrepair. Their removal did not damage the chapel.

A major attribute of the chapel is the peaceful setting, on a hill overlooking the cemetery on one side and distant blue hills on the other.

Significance: Period - 1890-1899; Areas of significance - architecture.

Specific dates - 1866. Edward Northcraft, architect; Ralph Smith, builder

American Gothic Revival tastes ran the gamut from frilly to stark. San Marcos' Cemetery Chapel is in the latter category, "Carpenter Gothic". The open air plan also recalls the brush arbors that served the first pioneers until they could afford genuine sanctuaries.

United States Department of the InteriorNational Park Service

National Register of Historic Places Inventory—Nomination Form

received
date entered

Continuation sheet

Item number

A11

Page 25

The earliest settlers used a plot in the Lindsey addition, a block from where the First Methodist Church now stands, as a cemetery. Mrs. W.W. Moon was the first person buried there, in 1846. The City of San Marcos Cemetery Association in 1876 bought a plot further from the town where a few people, including six slaves, had already been interred. This became the present cemetery.

Before the chapel was built, mourners had to make a long carriage journey into town for the service and then another out to the cemetery. This was too time consuming for those who wanted to be back on the farm by dark. Also, cemetery chapels were "in vogue" across the southwest where mild weather made them possible. So architect Edward Northcraft and builder Ralph Smith were contracted in 1886 to erect a chapel on a cross plan. They would have five months to complete the \$450 structure. Their work was well received. The chapel has hosted the last rites of the town's most respected citizens and veterans of the Civil, Spanish-American, and World Wars.

Bibliography:

Recorded Texas Historic Marker file, Texas Historical Commission, Austin, Texas.

<u>Historical Markers in Hays County</u> (see general bibliography for full listing),
p. 150.

The Free Press, January 7, 1886.

Speech by Tula Townsend Wyatt, November 11, 1966, recorded by the Hays County Historical and Genealogical Society, on file at the San Marcos Public Library.

Geographical data: Acreage - less than one acre
UTM reference - 14 / 600690 / 3306500

Verbal Boundary Description - The chapel is located 400 ft. south of the southern-most extension of the 800 ft. contour line of a scarp that straddles State Highway 12. (The eastern 800 ft. line crosses Highway 12 about 400 ft. northwest of the city limit). The chapel's boundaries are shaped like a lozenge, the points of which are 35 ft. from the midpoints of the cruciform structure's end walls. The sides of the lozenge are, therfore, at 45° angles from the chapel walls and face (approximately) the cardinal directions. The structure and immediate environs are included.

WASO Form - 177 ("R" June 1984)


Cemetery Chapel, San Marcos Cemetery

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES EVALUATION/RETURN SHEET

(San Marcos MRA) Hays County TEXAS Fed. Reg. Date: ____ Date Due: 12/10/83 Action: __ACCEPT _ /2/1/83 resubmission nomination by person or local government owner objection Federal Agency: _____ appeal request appeal NR decision __ sample Substantive Review: Reviewer's comments: Recom./Criteria____ Reviewer ____ Discipline _____ ____ see continuation sheet Nomination returned for: _____technical corrections cited below __substantive reasons discussed below 1. Name 2. Location 3. Classification Present Use Ownership Status Category Accessible **Public Acquisition** 4. Owner of Property 5. Location of Legal Description 6. Representation in Existing Surveys ☐ yes no Has this property been determined eligible? 7. Description Check one Condition Check one original site unaltered deteriorated excellent ruins altered moved good date unexposed ___ fair Describe the present and original (if known) physical appearance summary paragraph completeness ☐ clarity alterations/integrity dates boundary selection

8. Significance	330 94 9	And the second of the second o		
Period Areas of Significance-	Check and justify below			
Specific dates Statement of Significance (in one)	Builder/Architect paragraph)			
summary paragraph completeness clarity applicable criteria justification of areas checked relating significance to the resc context relationship of integrity to signification of exception other				
9. Major Bibliographical Reference	es			
10. Geographical Data	1000 A			
Acreage of nominated property Quadrangle name UTM References				
Verbal boundary description and	ustification			a at the second
11. Form Prepared By				
12. State Historic Preservation Of The evaluated significance of this			189 18 m - 1991	
national State Historic Preservation Office	statelocal signature			
title da	te			
13. Other	All the second second	The state of the s		
☐ Maps ☐ Photographs ☐ Other				
Questions concerning this nomina	tion may be directed to			
Signed	Date		Phone:	



Historic Resources of San Marcos San Marcos, Hays County, Texas #11. Cemetery Chapel

Photo by Lissa Anderson, April, 1982. Negative property of HASM, on file at SMPL.


East oblique, camera facing west. Photo 51 of 150.



Historic Resources of San Marcos San Marcos, Hays County, Texas #11. Cemetery Chapel

Photo by Lissa Anderson, April, 1982. Negative property of HASM, on file at SMPL.

South oblique, camera facing north. Photo 52 of 150.



Historic Resources of San Marcos San Marcos, Hays County, Texas #11. Cemetery Chapel

Photo by Lissa Anderson, April, 1982. Negative property of HASM, on file at SMPL.

Detail of interior truss and roof system. Photo 53 of 150.

Please refer to the map in the Multiple Property Cover Sheet for this property

Multiple Property Cover Sheet Reference Number: 64000853