NPS Form 10-900-a (3-82)

### United States Department of the Interior National Park Service

# National Register of Historic Places Inventory—Nomination Form

For NPS use only received

date entered

Continuation sheet		Item number All		Page 7		
4		Name: Moore Groo	cery Company	(Common name, King F	eed Company)	
		Location: 101 S	outh Edward	Gary Street		

Classification: Category - building; Ownership - private; Status - occupied; Accessible - yes, unrestricted; Present use - commercial.

Owner of property: Mrs. Lotha Mae King 102 Norcrest San Marcos, Texas 78666

Description: Condition - good; Altered; Original site.

On the edge of the downtown area near the railroad tracks, is the Moore Grocery Company Building, now the King Feed Company. The one-story structure, with basement and mezzanine, is of buff brick which has been painted white on the exterior. The low gabled roof is masked on the west facade by a stepped parapet. A low, shed-roofed, porch is also on this side. On the south wall are a small office addition of brick, and a corrugated-metal dock room.

The north wall is pierced at ground level by seven basement vents. The five windows on the first floor have four-over-four lights, while the five windows on the second level have single panes. All openings are under segmental rowlock arches, and the windows are barred. Similar fenestration is found on the south wall, but is obscured by the dock addition. A large double door and a sliding door allow access. The west, entrance facade contains two sets of double doors under arched and barred transoms flanked by two similar windows with four-over-four lights. Between the doors is a modern plateglass window.

Several features distinguish the interior. A wooden loft against the south wall is reached by a single flight of wooden stairs. Toward the store's rear is the original Otis Elevator on a rope and pulley system. It is still used. The office is enclosed within the southeast corner and embellished with beaded ceilings and other wood finishes, and the metal addition is the original floor scale. There, one can read "Moore Grocery Co." painted on the sliding door. Wooden floors, lack of temperature control, and the musty odor of feed and plants enhance the early 20th century atmosphere.

Alterations have been few. An unobtrusive, low, clay-brick room was added to the rear by Mr. Moore. The aforementioned additions all appear to have been built shortly after the erection of the main structure. The plate glass window and three aluminum doors are the only noticeable modern changes.

OMB No. 1024-0018 Exp. 10-31-84 NPS Form 10-900-a (3-82)

United States Department of the Interior National Park Service

# National Register of Historic Places Inventory—Nomination Form

For NPS use only received date entered

OMB No. 1024-0018

Exp. 10-31-84

Continuation sheet	Item number A11	Page 8
		1

Significance: Period - 1900- ; Areas of significance - commerce; Specific dates - 1913.

In some towns, there are buildings that encapsulate a certain aspect of local history. In San Marcos, the building at 101 South Edward Gary portrays early 20th century, middle-class commerce. It housed the Moore Grocery Company and is presently home to the King Feed Company. Neither business has obscured the original fixtures or the stately utilitarian design, which is the best preserved of its type and period in town.

John. M. Moore had the store built in 1913. His wholesale grocery company competed with the only other similar outfit, the Southern Grocery Company. A 1918 fire, rumored to have been set to hide stolen rationed goods, destroyed the latter store. Moore employed several salesmen to sell staples, canned goods, candy, dried fruit, and general merchandise to local and area retailers. Occasionally he sold to institutions such as the Austin State Hospital and the State Blind School. The company seems to have dealt in all types of neccesities except highly perishable fruits and vegetables. Upstairs, tires and tubes were for sale. Deliveries arrived via railroad and unloaded at the spur that ran alongside the building. Bulk items were repackaged for sale to retailers. Moore added a room to the rear to contain low wire-mesh tables for drying and/or storing fruit and stocks of matches. The fire wall between this room and the main building recently saved the store from complete destruction by arson.

After a brief period as the Groce-Wearden Grocery Company, the building was sold in 1955 to Clarence T. King, who moved his feed business there. Remaining in place are the original Otis Elevator, the floor scale, wood floors, and sliding doors. The entire atmosphere is reminiscent of the decades when these businesses were central to the community.

Bibliography:

San Marcos Record, October 8, 1959. Lotha Mae King, unpublished written material, March 1982. On file at San Marcos Public Library. Interview with Bess Moore Hopson, July 7, 1982.

Geographical data: Acreage - less than one acre UTM reference - 14 / 602570 / 3305970

Verbal Boundary Description - Original Town Site, Block 6, Lot 5. Behind the building there are large feed hoppers and a modern cinder-block, lawn-mower shop. On the south is a parking lot. Although these are under the same ownership, they do not add to the nominated building's significance and are on different lots and detached from the main building. Therefore, they are not included in the legal description. WASO Form - 177 ("R" June 1984) UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

#### NATIONAL REGISTER OF HISTORIC PLACES EVALUATION/RETURN SHEET

Moore Grocery Company (San Marcos M	<u>(RA)</u>	
Hays County TEXAS		
TEARD		Working No. 1-14-83
		Fed. Reg. Date: 2.7,84
		Date Due: $8/11/83 - 8/28/83$
		Action: ACCEPT 8/26/83
	Enter	red in the RETURN
nomination by person or local government	Natio	Federal Agency:
owner objection		Federal Agency:
appeal		
Substantive Review: sample requ	uest 🗌 appeal	NR decision
Reviewer's comments:		
		Recom./Criteria
		Reviewer
		Discipline
		Date
		see continuation sheet
Nomination returned for: technical corrections of substantive reasons dis		
1. Name		and a software of a relative ball a second ball
2. Location		
3. Classification		
Category Ownership Public Acquisition	Status Accessible	Present Use
4. Owner of Property	31-01572 31-01572	
5. Location of Legal Description		
6. Representation in Existing Surveys		
Has this property been determined eligible?	res 🗌 no	4 Q
7. Description		
Condition	Check one	Check one
excellent deteriorated	unaltered	original site
good I ruins	altered	moved date
air unexposed		
Describe the present and original (if known) physical ap	opearance	
summary paragraph		

summary paragraph
completeness
clarity
alterations/integrity
dates
boundary selection

#### 8. Significance

Period Areas of Significance—Check and	justify	below
--	---------	-------

Specific dates Builder/Architect Statement of Significance (in one paragraph)

summary paragraph	
Clarity	
applicable criteria	
justification of areas checked	
relating significance to the resource	
context	
relationship of integrity to significa	nce
□ justification of exception	
other	

#### 9. Major Bibliographical References

10.	Geog	raph	ical I	Data

Acreage of nominated property _	August and
Quadrangle name	
UTM References	

Verbal boundary description and justification

## 11. Form Prepared By

12. State Historic Preservation Officer Certification	ation	and the second	1
The evaluated significance of this property with	nin the state is:		
national state	local	and the state of the	
national state			
State Historic Preservation Officer signature			
title date	1		
13. Other	The second s	and the second second	
Maps			
Photographs			
Other			
Questions concerning this nomination may be o	directed to	and the second	and the second
Signed	Date	Phone:	

Comments for any item may be continued on an attached sheet



Photo by Lissa Anderson, July, 1982. Negative property of HASM, on file at SMPL.

Northwest oblique, camera facing southeast. Photo 17 of 150.



Photo by Marian Oles, June, 1982. Negative property of Marian Oles, Studio II.

Northwest oblique, camera facing southeast. Photo 18 of 150.



Photo by Lissa Anderson, July, 1982. Negative property of HASM, on file at SMPL.

Southwest oblique, camera facing northeast. Photo 19 of 150.




Photo by Lissa Anderson, May, 1982. Negative property of HASM, on file at SMPL.

Interior - detail of Otis elevator. Photo 20 of 150.

# Please refer to the map in the Multiple Property Cover Sheet for this property

Multiple Property Cover Sheet Reference Number: 64000853