National Register of Historic Places Inventory—Nomination Form

For NPS use only received date entered

Continuation sheet

Item number all

Page 65

SITE NO. 23

NAME

Tom and Martha Rogstad, farm

LOCATION

112 miles west of Clifton, Bosque County,

Texas, on W. Gary survey

OWNERS

Charles B. Richards, Jr. and Dudley C. Haas

Box 785

Waco, Texas 76703

PRESENT USE

Private residence, agriculture

CATEGORY

Buildings

STATUS

Unoccupied

QUADRANGLE NAME

Cranfills Gap, Texas

OUADRANGLE SCALE

1:24000

UTM REFERENCE

14/615760/3515150

ACREAGE

about 3½ acres

PHOTO REFERENCE NO.

35

DESCRIPTION

The Tom and Martha Rogstad farm includes a one-and-a-half-story frame house that is similar to the Colwick house (no. 22). It stands on level terrain at the top of Rogstad Mountain. Presently unoccupied, it is in only fair condition. The house is virtually unaltered, and retains its integrity to a remarkable degree. The plan of the house is T-shaped, although a small addition has been built onto the rear. A shed-roof porch, with turned wooden posts and jig-cut wooden brackets, extends across the front, or east, elevation. Windows with both two-over-two and four-over-four-lights pierce the walls. A small and square window with four lights is found above the porch roof, centered over the single front door. A composition-shingle roof with intersecting gables shelters the structure, and a corbeled brick interior chimney rises

National Register of Historic Places Inventory—Nomination Form

For NPS use only received date entered

Continuation sheet

Item number all

Page 66

from the east gable end. A one-room stone structure, which is believed to have been used as a smokehouse, stands a few feet north of the house. Other outbuildings that contribute to the historic character of the farm include two barns, one of board-and-batten construction, and the other with metal covering.

SIGNIFICANCE

Located on one of the oldest farmsteads within the entire Norwegian Settlement, the Tom and Martha Rogstad farm remains virtually unaltered since its completion in 1893. It represents one of the most outstanding late 19th-century farm houses in the area. According to one of their grandchildren, it was built by the Norwegian carpenter, Johan Nordahl, after an 1892 fire destroyed the old stone house of Berger and Ann Rogstad. The foundation of this structure is said to still exist on the property.

National Register of Historic Places Inventory—Nomination Form


For NPS use only
received
date entered

Continuation sheet

Item number all

Page 67

AREA TO BE NOMINATED



National Register of Historic Places Inventory—Nomination Form

For NPS use only received date entered

Continuation sheet

Item number

Page 4 4t

Multiple Resource Area Thematic Group

Stat		—		
Non	nination/Type of Review	Entonod	1	Date/Signature
31.	Ringness, Jens and Kari, Farm	Entered in the National Registe	Keeper Attest	1/22/83 Helous Byen
32.	Rogstad, Tom and Martha,	Entered in the National Register	Keeper	7/22/83 Delous Byen
	Farm		Attest	
33.	Schultz, Tobias and Wilhelmine, Farm	Entered in the National Register	Reeper	7/22/83 Delmas Byen
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Entered in the	Attest	
34.	Shefstad, Gunarus and Ingerborg, House	National Register	Reeper	7/22/83 Delores Byen
			Attest	
35.	Upper Settlement Rural Historic District	Substantive Review		Beth Giosoener 7/20/8
~		Entered in the	Attest	
36.	Wilson Homesite	National Register	Keeper	7/22/83 Allous By
			Attest	
37.			Keeper	
			Attest	
38.			Keeper	
			Attest	
39.			Keeper	
			Attest	
40.			Keeper	
			Attest	

Rogstad, Tom and Martha, Farm (Norwegian Settlement of Bosque County TR)
Bosque County
TEXAS

	<u>.</u>
	Working No. JUN 9 1983
	Fed. Reg. Date: 2.7.94
	Date Due: 7/7/83-7/24/83
	Action: ACCEPT_7/22/8
resubmission	Entered in the RETURN
nomination by person or local government	National Register REJECT
owner objection	Federal Agency:
appeal	
Substantive Review: sample request	appealNR decision
Reviewer's comments:	
	Recom. / Criteria
	Reviewer
	Date
	see continuation sheet
substantive reason:	s discussed below
1. Rame	
2. Location	
3. Classification	
Cologory Suscretip Status Procest Use	
Public Acquisition Accessible	
4. Owner of Property	
5. Location of Legal Description	
6. Representation in Existing Surveys	
has this property been determined slightle?	
7. Description	对自己的对抗性的
Sendition Check one Check one	
	. dree of the constant of the seasons
feir unexposed	
Bosoribe the present and original (if known) physical appearance	
summary paragraph	
completeness	
clarity	
alterations/integrity	
dates	
boundary selection	

8. Significance		
Period Areas of Significance. Check and justify below	Halpharya e	Andre of the second
Specific dates Builder Architect		ALTO SELECT SE SILVE SE
Statement of Significance (in one paragraph)		
2013年68年1月1日		
summary paragraph		
completeness		
applicable criteria		
justification of areas		
relating significance to		
the resource		
relationship of integrity to significance		
justification of exception		
other		
9. Major Bibliographical Referen	nces	
Acresps of nominered property		
11. Form Prepared By		
12. State Historic Preservation	Officer Certification	
The evaluated significance of this property within the scate is:		
netionelstatelocal		
State Historic Preservation Officer signature		
Stile date		
13. Other		
Maps Photographs Other		
Questions concerning this nomina	tion may be directed to	
Signed	Date	Phone: 202 272 - 3504

Comments for any item may be continued on an attached sheet



The Norwegian Settlement of Bosque County

Site No. 23, Tom and Martha Rogstad Farm, $11\frac{1}{2}$ miles west of Clifton, Bosque County, Texas

Photograph: March 1979, by Daniel Hardy On file, Texas Historical Commission View of front facade, looking northwest Photo 35 of 72

Please refer to the map in the Multiple Property Cover Sheet for this property

Multiple Property Cover Sheet Reference Number: 64000849