## United States Department of the Interior National Park Service

### National Register of Historic Places Inventory—Nomination Form

For NPS use only
received
date entered

Continuation sheet

Item number all

Page 39

SITE NO. 14

NAME

Wilson homesite

LOCATION

314 miles west of Clifton, Bosque County, Texas,

on F. Wilson survey

OWNER

Henry Sanders

Route 2

Clifton, Texas 76634

PRESENT USE

Ruins, agriculture

CATEGORY

Building, site

STATUS

Unoccupied

QUADRANGLE NAME

Sugarloaf Mountain, Texas

QUADRANGLE SCALE

1:24000

UTM REFERENCE

14/629830/3516500

ACREAGE

less than 1 acre

PHOTO REFERENCE NO.

24

#### DESCRIPTION

The Wilson homesite is located on level terrain at the southern end of Bee Rock Flats, in a remote location that makes it almost inaccessible by car. According to local residents, the structure burned around 1950; thus it now stands without a roof. The house was rectangular in plan, had a gabled roof, and faced west. Its plaster finish has deteriorated to such an extent that the limestone construction is visible, along with the original mud and clay mortar. Large stone lintels span each of the openings, but all of the original doors and window sashes are gone. The ends of the north and south walls are steeply pitched. An exterior stone chimney rises from the north end, and window openings on both floors flank either side of this chimney. On the south wall, a central doorway and a window opening pierce the ground level and an off-center doorway pierces the gable. An external stairway probably extended from the southwest corner of the house to this doorway, allowing access to a loft. A concrete wall and stone-lined underground cistern are located west of the house. Other significant features

## United States Department of the Interior National Park Service

### National Register of Historic Places Inventory—Nomination Form

For NPS use only received date entered

Continuation sheet

Item number all

Page 40

on the farm include the remains of a dug-out cellar, the foundations of two outbuildings, and what may be the graves of the settlers. A rich surface scatter of potshards and historic refuse was observed.

#### SIGNIFICANCE

This housesite, which has been abandoned since it burned about 1950, was apparently the home of either Fred or John Wilson. Its age is unknown, but its construction with mud and clay mortar seems to indicate an early date, possibly to the 1860s. Close inspection of the site revealed a quantity of crockery shards, wood fragments, and other historic objects that argue for its archeological potential.

#### **United States Department of the Interior** National Park Service

## National Register of Historic Places Inventory—Nomination Form


For NPS use only received date entered

Continuation sheet

Item number all

Page 41

AREA TO BE NOMINATED



# **United States Department of the Interior**National Park Service

# National Register of Historic Places Inventory—Nomination Form

For NPS use only received date entered

Continuation sheet

Item number

Page 4 14

Multiple Resource Area Thematic Group

Stat	A STATE OF THE STA			Data/Signature
Non	nination/Type of Review	Entered in the	1	Date/Signature
31.	Ringness, Jens and Kari, Farm	National Regist		1/22/83 Allows Byen
32.	Rogstad, Tom and Martha,	Entered in the National Register	Attest	7/22/83 Delous Byen
		Entered in the	Attest	
33.	Schultz, Tobias and Wilhelmine, Farm	National Register	Reeper	7/22/83 Delmas Byen
		Water Y Ve 450	Attest	
34.	Shefstad, Gunarus and Ingerborg, House	Entered in the National Register.	Reeper	7/22/83 Delous Byen
			Attest	
35.	Upper Settlement Rural Historic District	Substantive Review	Keeper	Beth Giosoena 7/20/83
			Attest	
36.	Wilson Homesite	Entered in the National Register	& Keeper	7/22/83 Allons By
			Attest	
37.			Keeper	
			Attest	
38.			Keeper	
			Attest	
39.			Keeper	
			Attest	
40.			Keeper	
			Attest	

United States Department of the Interior National Park Service

> Wilson Homesite (Norwegian Settlement of Bosque County TR) Bosque County TEXAS

		20
	Working No. JUN 9 198	33 .
	Fed. Reg. Date: 2.7.80	f
	Date Due: 7/7/83-7/24	183
	: 4-41 7	122/83
resubmission	Entered in the REJECT	
nomination by person or local government	Entered in the REJECT	
owner objection	National Register Federal Agency:	
appeal		
	appealNR decision	
Reviewer's comments:		
	D /D	
	Recom. / Criteria	
	Reviewer	
	Discipline	
	Date	
	see continuation sh	eet
Nomination returned for:technical correctionssubstantive reasons		
1. Name		
2. Location		
3. Classification		
Cologory Gunorohia Status Process Use		
Public Acquisition Accessible		
4. Owner of Property		
4. Owner or Property		
5. Location of Legal Description		
6. Representation in Existing Surveys		
has this property been determined eligible?	yes no	
7. Description		
good ruins shored moved date		
Describe the present and original (If known) physical appearance		
summary paragraph		
completeness		
clarity		
alterations/integrity		
dates		
boundary selection		

8. Significance		
Period Areas of Significance. Check and justify below		reignam Francisco nomica
Specific dates Bullder Architect		Managar
Statement of Significance (in one paragraph)		
summary paragraph completeness clarity applicable criteria justification of areas checked relating significance to the resource context relationship of integrity to significance justification of exception other		
9 Major Bibliographical Beforence		
9. Major Bibliographical Reference		
Acresps of nominated property		
11. Form Prepared By		
12. State Historic Preservation Off The evaluated significance of this property enthin the state is:netionalstatelocal  State Historic Preservation Officer signature  State	icer Certification	
13. Other Maps		
— Photographs — Other		
Questions concerning this nomination	may be directed to	
Signed	Date	Phone: 202 272-3504

Comments for any item may be continued on an attached sheet



The Norwegian Settlement of Bosque County

Site No. 14, Wilson Homesite, 3½ miles west of Clifton, Bosque County, Texas Photograph: July 1979, by Daniel Hardy On file, Texas Historical Commission View of house, looking southeast Photo 24 of 72

# Please refer to the map in the Multiple Property Cover Sheet for this property

Multiple Property Cover Sheet Reference Number: 64000849