# National Register of Historic Places Inventory—Nomination Form

For NPS use only received MAY. 9 1983 date entered

1. Nam	10						
historia	Te Tal and resemble		er nicul	To a Register on the con-	ally Baro.		
historic	Round Rock Commerc	lal Histori	c Distric	tiloni ne verili interiore			
and/or common	afaces month in the said	La California	grand di	in 5 teor (and trib)	and the second	Acces.	
2. Loca	ation	E.					
	100 & 200 blocks	W. Main St	reet				
street & number	see continuation	sheet	A weeking	N/	A not for publica	ation	
city, town	Round Rock	N/Avic	inity of				
state Tex	as cod	de 048	county	Williamson	code	491	
3. Clas	sification			NICH TOWNS OF THE PARTY.			
Category	Ownership	Status	10 10 10 10 10	Present Use	0,70 - 120		
_X district	public	X occupi		agriculture	_X_ museum		
building(s)	X_ private	X_ unoccu	A STATE OF THE REAL PROPERTY.	X commercial	park	. 66	
structure	both	X_ work in		educational	private res	idence	
site object	Public Acquisition N/A in process	X yes: re	The same of the sa	entertainment government	religious		
object	being considered	yes: ur		industrial	transporta	tion	
	de sine out are the party	no	a Belleria	military	other:		
name							
se	e continuation shee					7 50.28 287 9	
street & number		N/A vic		state			
street & number		N/A vic					
street & number city, town 5. Loca	ation of Leg	N/A vic	criptic	n			
street & number city, town  5. Loca courthouse, regi	ation of Leg	N/A vic	criptic	n			
street & number city, town  5. Loca courthouse, regi	ation of Leg	N/A vic	criptic	n	Tevas		
street & number city, town  5. Loca courthouse, regi street & number city, town Ge	ation of Leg stry of deeds, etc.	N/A vic	County Cou	orthouse '	Texas	1016	
street & number city, town  5. Loca courthouse, registreet & number city, town  Ge  6. Rep	ation of Leg stry of deeds, etc.  orgetown resentation	N/A vice al Description Control of the N/A vice al Descri	County County Sting S	orthouse '		X n	
street & number  city, town  5. Loca  courthouse, reginerated & number  city, town  Ge  Repl  title  Hist	ation of Leg stry of deeds, etc.	N/A vice al Description Control of the N/A vice al Descri	County County Sting	on orthouse ' state	gible? yes	X n	
street & number  city, town  5. Loca  courthouse, reginerated & number  city, town  Ge  6. Repl  title  Hist	ation of Leg stry of deeds, etc.  orgetown resentation oric Sites Inventor	N/A vice al Description Control of the N/A vice al Descri	County Co	state Surveys  Derty been determined elign federal state	gible? yes		

### 7. Description

Co	ndition
	excellent
X	good

X fair

\_\_ deteriorated \_\_ ruins \_\_ unexposed Check one
X unaltered
X altered

Check one

X original site
X moved d

date Site #23, 1976

Describe the present and original (if known) physical appearance

The Round Rock Commercial Historic District is an assemblage of small commercial buildings, mainly of limestone ashlar, in the business section of a Central Texas town. The 22 contributing structures included herein were mainly constructed in the last quarter of the 19th century, and include handsome verancular and Italianate stone buildings originally used for retailing, offices, saloons, and meeting halls. The colorful history of Round Rock in the later 19th century is embodied in this commercial historic district.

The Round Rock Commercial Historic District is a concentration of 25 stone-masonry, predominately one-story, commercial buildings built during the last quarter of the 19th century. Stylistically, the buildings differ from many other Central Texas towns where brick was more commonly used. The vernacular, commercial architecture is characterized by stone masonry, load-bearing walls. The parapeted cornices are simply detailed in stone, and conceal sloping roofs. Originally both sides of the Main Street had tin-roofed, continuous store-front canopies the full width of each business establishment. Scattered remnants of these canopies remain in place, although most of the facades have been slightly altered. The district is visually defined by similarities in use, design, materials, scale, period of construction, and relationship to the street and sidewalk. With the exception of the Nelson Hardware building, with its handsome facade fabricated in St. Louis, the buildings in the district are all the work of local builders and craftsmen.

The historic district forms an approprate rectangle, bounded on the west by the east side of May Street, and on the east by a group of governmental buildings. The alley between Main Street (formerly Georgetown Avenue) and Liberty Avenue forms the northern boundary, while the alley between Main Street and Bagdad Avenue forms the southern limits of the district. There is an extension at the southwestern corner of this rectangle which includes property located just south of the alley between Main Street and Bagdad Avenue. This property faces directly onto Mays Street, while the rest of the nominated property faces onto East Main.

Main Street has been the center of the city's commercial activity since the new town of Round Rock was developed in 1876 at the southern terminus of a railroad line. The 100-foot-wide Main Street runs parallel with the railroad tracks less than two blocks away, located on a gentle slope south of Brushy Creek.

The section of Main Street included in the district was platted to serve as the commercial center of New Round Rock, as it was called until 1891. A spurt of building construction in 1876 and again in 1880 virtually completed the 100 block of East Main Street, leaving only a few lots vacant. Alleys running parallel with Main Street separate the historic district from the rest of the block.

### National Register of Historic Places Inventory—Nomination Form

For NPS use only received date entered

Continuation sheet

Item number

Page

The district encompasses the following addresses:

East Main Street: 101 through 121; 100 through 118

200 through 208; and 203.

South Mays Street: 107, (Masonic Lodge)

### National Register of Historic Places Inventory—Nomination Form

For NPS use only received date entered

Continuation sheet

Item number

4

Page

PROPERTY OWNERS

Map #	Block #9	Map #	Block #22
map ir	BIOCK #5	riap #	BIOCK WZZ
1	John Robertson	11	William & Sondra Stewart
	407 West Main Street		7210 Acacia
	Round Rock, TX 78664		Leander, TX 78641
2	Earl Palmer	12	Martin & Evelyn Kermacy
	103 East Main Street		2816 Woolridge Dr.
	Round Rock, TX 78664		Austin, TX 78703
3	Gensie B. Hemphill	13	Jack & Sue Hoover
	1400 Wathen		P.O. Box 356
	Austin, TX 78703		Round Rock, TX 78664
4	Larry Tonn	14, 15	Hudson Enterprise
	1700 Egger Avenue		110 East Main Street
	Round Rock, TX 78664		Round Rock, TX 78664
5	Round Rock Printing	16	William K. Todd
	P.O. Box 542		P.O. Box 428
	Round Rock, TX 78664		Round Rock, TX 78664
6	Travis Johnson	17	Bo-Kay Florist
	P.O. Box 218		P.O. Box 461
	Round Rock, TX 78664		Round Rock, TX 78664
7	Sammie Lou Maberry Estate	18	L. Hughes & John Carter
	3856 Arroyo Road		P.O. Box 445
	Fort Worth, TX 75109		Round Rock, TX 78664
8	Ruby Fisher	18	First National Bank
	1633 East Manor		P.O. Box 5
	Corpus Christi, TX 78412		Round Rock, TX 78664
9, 10	Xenia Voigt		Block #21
	P.O. Box 36		
	Round Rock, TX 78664	20	William Wilson 4502 College Park
25	Masonic Lodge #227		Dallas, TX 75229
	P.O. Box 101		
	Round Rock, TX 78664	21	Eugene O. Quick
			P.O. Box 278
			Round Rock, TX 78664

# National Register of Historic Places Inventory—Nomination Form

For NPS use only received date entered

Continuation sheet

Item number

4

Page

#### PROPERTY OWNERS (Cont.)

Map #	Block #21 (Cont.)
22	T.E. Nelson Estate 1552 American Bank Tower Austin, TX 78701
23	Round Rock Chamber of Commerce 214 East Main Street Round Rock, TX 78664
	Block #10
24	Nelson Hardware Joint Venture 402 West Seventh Street Austin, TX 78701

# National Register of Historic Places Inventory—Nomination Form

For NPS use only received date entered

Continuation sheet

Item number

7

Page

Active for over 107 years, Round Rock's commercial buildings underwent intense retail use, alternating with periods of vacancy. Several structures burned during the 19th century, leaving only masonry walls standing. Fire was a cause for drastic alterations especially in the case of the two buildings on the northwest corner of the intersection of Lampasas and East Main Street. Following a fire sometime between 1916 and 1925, the two-story building occupying the corner site was reduced to 14-foot stone walls; about 1920, brick veneer was applied to the exposed stone street walls of buildings at 116 and 118 East Main. This marked the first major use of brick within the downtown historic district. Alterations to other buildings include the painting of stone walls, applying stucco, the remodeling of store entrances and display windows, and the removal and/or replacement of storefront canopies. Store owners invariably "modernized" their buildings to make their store attractive by standards of their time. Such modernizations have resulted in changes to the interiors of the majority of the structures in the district, although the Economy Drug Store's interior (circa 1905) has

Previous uses of the buildings include the selling of groceries, clothing, notions, furniture, crockery, dry goods, confections, drugs, millinery, metal, harnesses, paints and oils, gentlemen's furnishings, feed, hardware, fruit, jewelry, and coffee. Trades and services formerly found in the buildings include banks, post office, professional offices, auto repair, tin shop, telephone exchange office, cobbler, carriage trimmer, barber shops, cleaning-and-pressing, and restaurant. Pool halls, saloons, and general stores were common occupants. The most unusual resident was a broom factory. Lodges and meeting rooms were prominent uses of the second floors of several of the two-story buildings.

survived virtually untouched, complete with original soda-fountain stools.

Some of the buildings which characterize the district are

Old Broom Factory (#11)

The Old Broom Factory is a two-story, limestone building in Italianate style prominently located on the northeast corner of Mays Street and East Main. On the front facade the arched openings of the first floor are semi-circular, while those of the second floor are segmental. The front facade is capped by a stepped parapet of stone. The stone around the openings is coursed, dressed ashlar with a drafted margin. The windows have a dropped keystone in the arch above, and four-over-four lights. The Sanborn Insurance maps indicate that the building was built in 1880. Currently the structure is being restored, and a missing arch has been rebuilt.

Otto Reinke Building (#12)

The Otto Reinke Building is another prominent Italianate structure built in 1879. It was gutted by fire in 1963, leaving only the limestone walls. The

# National Register of Historic Places Inventory—Nomination Form

For NPS use only received date entered

Continuation sheet

Item number

7

Page

2

fire-damaged building remained vacant for some time, and in 1970 it was repaired and the interior modernized. Changes in glazing material and window sashes mark several deviations from the original appearance. The round-arch openings on the first floor, the segmentally arched openings on the second floor, the regular, smooth-coursed limestone front with rusticated, projecting quoins all survived the fire and were preserved. The full-width, dentilated cornice has a curved pediment in the center.

#### Economy Drug Store (#21)

The Economy Drug Store Building is a singular specimen, for it is a totally unaltered commercial building in downtown Round Rock. It is a one-story, stone building with a cast-iron and pressed-tin facade. The large expanses of glass were undoubtedly progressive for the time and place. The a-b-a rhythm of its openings is repeated in the cornice. The interior balcony, an oak pharmaceutical desk, oak shelving, oak display cases and pressedmetal ceilings are all intact interior features, making it one of the few unaltered interiors in the district.

#### Nelson Hardware (#24)

The Nelson Hardware Building is a two-story, stone, Italianate commercial structure on a prominent corner at East Main and Lampasas streets. The castiron and pressed-tin front elevation is a splendid example of the way turn-of-the-century retailers in Central Texas, using standard catalog items, enhanced the appearance of their stores. There is a prominent cornice with brackets and a triangular pediment with the date 1900 stamped on it. The corner entrance to the store is marked by a less prominent pediment. The openings on the stone-masonry portions of the buildings are generally segmentally arched. The building is currently undergoing restoration, and most of the sashes have been removed. The elevation facing the alley is all of stone masonry and is capped by a stepped stone parapet.

#### Individual listings of the buildings within the district

(Information includes map reference number, the historic name, if known; (present occupant) - address; date or period of construction; category - see Definition of Categories in Item 8; brief physical description.

1. Kopperal's General Store (Fabric Designs) - 101 East Main Street. Built in 1876. Contributing. A small, one-story, stone-masonry building occupying a corner site. The street elevations have been stuccoed and the original openings have been replaced. There have been minor alterations.

### National Register of Historic Places Inventory—Nomination Form

For NPS use only
received
date entered

Continuation sheet

Item number

7

Page

3

- 2. Miller's Exchange Bank (Earl's Brushy Creek Gallery) 103 East Main Street. Built in 1876. Contributing. A small, one-story, stone-masonry building. The front elevation collapsed in the early part of the 20th century and was replaced with a wooden front. The present owner removed the wooden facade, and in 1972 built the existing masonry facade. Minor alterations have been made.
- 3. (Sam Bass General Store, vacant) 105 East Main Street. Built in 1876. Contributing. This store facade has undergone relatively little alteration. The three-bay front with segmental-arch openings and a simple cornice make this one of the best remaining one-story buildings.
- 4. (Maschall and McNeary, Attorneys) 109 East Main Street. Built in 1885. Contributing. A small, one-story, stone-masonry building. This is a simple, two-bay building with round arches. It has been relatively unaltered.
- 5. (Round Rock Printing) 111 East Main Street. Built between 1916 and 1925. Contributing. This is one of the rare uses of brick. The brick appears to be a facing over stone. The vestiges of a cornice and the a-b-a rhythm of the openings outweigh the alterations which have been made.
- 6. (Round Rock of Music) 113 East Main Street. Built  $\underline{ca.}$  1920. Non-Contributing. This building is intrusive, as remodeling has destroyed the original front facade.
- 7. (Gus's Drug Store) 115 East Main Street. Built in 1885. Contributing. A small, one-story, stone-masonry building that has been stuccoed. The original openings have been replaced and a metal facade placed over the cornice. The building has undergone several alterations.
- 8. The Fair (vacant) 117 East Main Street. Built in 1891. Contributing. A long, one-story, stone-masonry building with handsome, arched openings on the alley elevation. The front has undergone alterations, including the addition of a concrete beam spanning the door and display areas, but the current owners are working with historic photographs to restore the three round-arch openings.
- 9. (Robertson's Gift Shop) 119 East Main Street. Built in 1881. Contributing. This is a one-story, stone-masonry building that has been stuccoed, possibly at a quite early date. The openings have been relatively unaltered.

# National Register of Historic Places Inventory—Nomination Form

For NPS use only received date entered

Continuation sheet

Item number

7

Page 4

- 10. Voight and Brady Grocery; also historically, W.J. Walsh General Merchandise (Kelly's Cleaners) 121 East Main Street. Built in 1877. Contributing. This building was originally mapped as a two-story structure, as verified by remaining physical evidence and historical photographs. This building was stuccoed quite early.
- 11. Shuey's Furniture Store; also known as Old Broom Factory (vacant) 100 East Main Street. Built in 1880. Contributing. This two-story, ashlar limestone building is one of the handsomest and most prominent in the district. It is undergoing restoration.
- 12. Otto Reinke Building (Round Rock Travel and Tours, and Round Rock Leader) 102 East Main Street. Built in 1879. Contributing. This is another prominent two-story building of the district.
- 13. (Round Rock Insurance and John's Barber Shop) 104 East Main Street. Built in 1947. Contributing. Although this building is less than 50 years old, its use, scale, and parapet qualify it as contributing to the district.
- 14 & 15. (White's) 108 & 110 East Main Street. Both were built in 1880. Non-contributing. Unsympathetic and recent board-and-batten upper facade.
- 16. (Round Rock Leader) 112 East Main Street. Built in 1881. Contributing. This building is one of the few buildings in the district where the openings have not been altered. For this reason the building is classified as contributing even though the cornice has been altered.
- 17. (Bo-Kay Florist)- 114 East Main Street. Built in 1881. Contributing. Although this building is more than 100 years old, a few alterations have been made.
- 18. (Round Rock Professional Building) 116 East Main Street. Built in 1880. Contributing. This building is classified as contributing even though the stone front was covered <u>ca.</u> 1920. The addition of the brick veneer at that time was in keeping with the scale and style of the district. These alterations were further changed later. The brick cornice remains intact.
- 19. (First National Bank) 118 East Main Street. Built in 1880. Contributing. This building is classified as contributing because the handsome, 1920s brick-veneer facade is more than 50 years old. The scale and architectural style contribute in a positive way to the historic district.

### National Register of Historic Places Inventory—Nomination Form

For NPS use only received date entered

Continuation sheet

Item number

7

Page

5

- 20. Anderson-Nelson Company (Photocopy & Mike Faulk and Associates, Architects, in the west half; vacant in the east half) 200 East Main Street. Built between 1902 and 1909. Contributing. This cast-iron facade that incorporates large expanses of glass for display windows is an fine example of a turn-of-the-century retail facades. The building has undergone relatively few alterations.
- 21. Economy Drug Store (Quick Pharmacy) 204 East Main Street. Built between 1902 and 1909. Contributing. This building has been in continual use as a pharmacy since it was built. There have been no interior or exterior alterations. The store-front canopy is intact, and many pharmaceuticals from the earliest years of operation are displayed inside.
- 22. Dr. Gregg's Office (vacant) 206 East Main Street. Built in the 1930s. Contributing. This structure is more than 50 years old, and makes a positive contribution to the entire district because of its use, style, and scale.
- 23. Andrew J. Palm House (Round Rock Chamber of Commerce) 208 East Main Street. Built <u>ca.</u> 1873; Contributing. Built ca. 1873; moved to this site in 1976. The Palm House is similar to other vernacular residences found near the Commercial District in its early days; an older residential neighborhood begins a block east of this structure, which was recently restored.
- 24. Nelson Hardware; "The Co-op" (vacant) 203 East Main Street. Built in 1900. Contributing. This two-story limestone building is architecturally important because of its pressed-tin facade.
- 25. Old Post Office Building (Masonic Lodge #227) 107 South Mays Street. Built in 1878. Contributing. This two-story building has ashlar limestone on the front and a handsome corbeled brick parapet above. The first-floor openings have round arches, while the openings on the second floor are segmentally arched.

### 8. Significance

Period prehistoric 1400–1499 1500–1599 1600–1699 1700–1799X 1800–1899X 1900–		community planning conservation economics education engineering exploration/settlement	military music philosophy politics/government	religion science sculpture social/ humanitarian theater transportation other (specify)
Specific dates	1870-1930	Builder/Architect	Unknown	September 1

#### Statement of Significance (in one paragraph)

The Round Rock Commercial Historic District is a well-preserved downtown area. First known as New Round Rock, in 1876 the town was laid out south of Brushy Creek in the limestone country of Central Texas. It grew up as a city linked to the Illinois and Great Northern Railroad, and its population grew to 1400 by 1890. After 1900 the town fell into a gradual decline which lasted until recent times, when a second period of growth began which is still underway. With a high concentration of vernacular and Italianate commercial architecture, the district retains much of its original character. Its constituent buildings serve as memorials for the early businesses and citizens of the area.

Originally the first settlement at Round Rock was located just north of Brushy Creek on the road now known as Chisholm Trail. This site was chosen because the stone ford there was widely known as a safe place to cross the creek, and the Military Road (named "Chisholm Trail" in 1968), which was laid out during the 1840s, made it a natural place for a town to grow up. In the 1850s the road became known as the Austin-Georgetown Road. This earliest settlement was known as Brushy Creek from 1847, when it was established, to 1854, when its name was changed to Round Rock. When the new town of Round Rock was laid out in 1876, south of Brushy Creek, it was named New Round Rock and the original settlement became known as Old Round Rock.

In 1876 the Illinois and Great Northern Railroad extended its service as far south as Round Rock. The new town site was platted by the Texas Land Company to coincide with what was then the southern terminus of the line. The impact of the railroad was so rapid that a tent city sprouted in 1876 at the new site. The initial downtown building boom, lasting five years, produced at least 13 stone masonry buildings of one and two stories. Stylistically, the buildings differ from those of other central Texas towns where brick was more commonly used. By 1878, Round Rock had 14 general stores, four drug stores, four lumber yards, one baker, and six hotels. The railroad tracks were located south of the downtown. There were numerous wood-frame commercial structures located on Bagdad Avenue, on West Main Street, and on Mays, Lampasas, and Shepard where they intersected Main Street. There was train service three times a day between Georgetown and Round Rock by 1895. By 1903 there were six rail lines in Williamson County, widespread changes such as shifts in population, increased land values, faster development and these brought better communications, and the shipment of large amounts of commodities. Towns like Old Round Rock, which were bypassed by the railroad, declined.

9. Major Bibliographical Re	eferences
Scarbrough, Clara Stearns. Land of Good Water Texas, History. Georgetown, Texas: Will Whiffen Marcus. American Architecture Since MIT Press, 1969.  ( See Continuate	iamson County S-n, 1976. 2 1780: A Guide to Styles. Cambridge:
10. Geographical Data	Ministration of the second and the second
Acreage of nominated property 4.23 acres  Quadrangle name Round Rock, Texas  UTM References	Quadrangle scale1:24000
A 1 4 6 2 6 9 6 0 3 3 7 5 7 9 0 Northing  C 1 4 6 2 6 8 0 0 3 3 7 5 7 3 0	B 1 14 6 2 6 9 8 0 3 3 7 5 6 2 0 Northing D 1 14 6 2 16 8 14 10 3 13 7 15 5 19 10
G	F
Verbal boundary description and justification  See continuation sheet	to an entre a transport de la la la la la company de la
List all states and counties for properties overlapping state $N/A$ code co	state or county boundaries unty code
	unty code
name/title Ruth Parshall, Architect & Preservorganization Carter & Parshall Associates  street & number 607 Nueces Street	date November 1982  telephone (512) 476-1812
	state Texas 78701
12 State Historic Preserv	ation Officer Certification
The evaluated significance of this property within the state is  national stateX_ lo	The same of the sa
As the designated State Historic Preservation Officer for the 665), I hereby nominate this property for inclusion in the Natiaccording to the criteria and procedures set forth by the Nati	onal Register and certify that it has been evaluated
State Historic Preservation Officer signature	Wis famille
title State Historic Preservation Officer	date/90pm/1983
For NPS use only I hereby certify that this property is included in the National Control of the Nation	

# National Register of Historic Places Inventory—Nomination Form

For NPS use only received date entered

Continuation sheet

Item number

8

Page

1

New Round Rock grew to a population of 1,200 by 1878, to 1,438 by 1890. A continuous decline through the first half of the 20th century was reflected in the 1900 Census, which listed 1,139 people. By 1920, the population had been reduced to 900. The City of Round Rock was incorporated in 1912.

In 1960 the recorded population of 2,348 was approximately twice that of 1878. After a modest increase in 1970 to 2,811, the 1980 census revealed an impressive gain with 12,740 people recorded. Recent economic developments have brought prosperity to the area again. Round Rock's proximity to Austin, and its location on a major interstate highway, have contributed to its status as a popular commuter town for many who work in the capitol city. Projections for 1990 are for continued population increases and comcomitant development. In the past this development has tended to be large scale, and tended to occur in peripheral areas and along major highways. Many downtown businesses have been attracted to the new retail strip developments, and the resulting exodus has endangered the vitality of the downtown commercial area.

One of the earliest industries attracted to new Round Rock was a commercial lime-manufacturing plant owned by William Walsh. His first lime-burning kiln was near Austin, but upon discovering a more suitable grade of limestone near Round Rock, he moved his business there in 1876. At the same time another important business was established, the Round Rock Broom Factory. It operated for many years, and occupied the two-story building at 100 East Main Street. Corn for making the brooms was imported from other states. Many of the merchants in Old Round Rock simply moved their businesses to new Round Rock. By 1877, New Round Rock had the following businesses: George M. Dilley Lumber, H.B. Sheppard General Merchandise (Sheppard was prominent in Old Round Rock), Tobin Drugs, Forwood & Cottingham Lumber, August Glober Hardware, Captain J.D.S. Morrow merchant, Henry Albert Highsmith Livery, M.D. Miller Exchange Bank, Round Rock Headlight (newspaper), Round Rock Hotel or Hart Hotel, E.P. Robinson Hardware & Dealer in Hides, bankers W.S. Peters and P.G. Peters, and attorney J.H. Robertson.

#### Significant Buildings and Organizations

The Masonic Lodge #227 Building (#25)

The Masonic Lodge #227 built the structure at 107 South Mays in 1878. The two-story, stone-masonry building was apparently built to house the lodge meeting space on the second floor while the first floor served as lease space. The fine quality of the brickwork detailing of this building represents an imaginative interpretation of the Italianate style, and contrasts with the austere limestone walls. One long-term tenant was the United States Post Office. To this date the Masons continue to meet in the building. The first floor is vacant now.

The Old Broom Factory (#11)

The original use of the building was as a dry goods, grocery, and general store. By 1885, Shuey's Furniture occupied the building. By 1896, the first floor was used by a confectionary and the second floor by an unamed lodge. There is conflicting information on the dates of occupancy by the Round Rock Broom Factory. By the turn of the century it was occupied by the broom factory,

### **National Register of Historic Places Inventory—Nomination Form**

For NPS use only received date entered

Continuation sheet

Item number

8

Page

until 1912 when the factory was relocated. At the 1904 World's Fair in St. Louis, the broom company became famous when it earned a gold medal for a broom designed and manufactured in Round Rock.

The Fair (#8)

The Fair was built sometime between 1886 and 1890. E.P.M. Robinson, whose initials EPR appear on the cornice is the owner credited with having it built. The most significant and enduring ownership of the building started in 1900 when the Walsh family, whose lime-manufacturing laborers were paid with tokens to be exchanged for goods, operated a "company" store on these premises until 1950.

The Nelson Hardware Building (#24)

This structure was originally built to house a private banking, hardware, and lumber business owned by several prominent families in Round Rock, including J.A. Nelson, C.A. Nelson, W.E. Henna, O.L. Brady, O.A. Voight, and J.E. Gustafson. John A. Nelson's bank was successful from the beginning, although the bank was discontinued in 1922. Later occupants of the building include a chicken hatchery, and a milk producers' cooperative (whence the recent common name, "The Co-op"). There is conflicting information on when this building was built. The front of the building clearly bears the date 1900, but the Sanborn maps indicate a stone building there, built in 1881. Architecturally the most pretentious structure in the district, the Nelson Hardware Building retains its finely detailed cast-iron and pressed-tin facade, fabricated by the Mesker Brothers of St. Louis. This lively interpretation of the Italianate style represented the most up-to-date taste, and was sure to attract the attention of the passerby.

The First National Bank (#18)

Sanborn insurance maps and historic photographs indicate that this originally was a two-story stone building, built in 1880, that housed a store selling dry goods, clothing, groceries, and notions. The use remained the same through 1909, and then sometime between 1909 and 1916 a fire or some other natural catastrophe destroyed the roof and second-floor framing. The 1916 Sanborn map for Round Rock shows a roofless structure with 14-foot stone walls. By 1925 the building had brick facing on two elevations, a concrete floor, and was occupied by a bank.

### Definition of Categories

Contributing:

A great majority of the buildings (22 of 25) in the district are classified as contributing. This category includes structures which are over 50 years old, which retain a significant amount of their historical and architectural integrity, and which reflect a vernacular commercial architecture. Some buildings have been classified as contributing in spite of a moderate amount of exterior alteration.

# National Register of Historic Places Inventory—Nomination Form

For NPS use only received date entered

Continuation sheet

Item number

8

Page 3

Non-contributing:

Only three structures are grouped in this category. These buildings are over 50 years old, but severe alterations have destroyed all of the original detailing, and fenestration. Their appearance detracts from the historical character of the district.

#### Justification of the Boundaries

The district includes virtually all of Round Rock's central retail area. The boundaries have been determined to obtain the highest concentration of little-altered, historic commercial buildings. Generally, residential neighborhoods and vacant land bound the district to the north. The southern and western boundaries are bordered by areas of mixed use and vacant land. The eastern edge is bounded by governmental buildings.

### National Register of Historic Places Inventory—Nomination Form

For NPS use only received date entered

Continuation sheet

Item number

9

Page

Alexander, Drury Blakeley. <u>Texas Homes of the 19th Century</u>. Austin: University of Texas Press, 1966.

Sanborn Fire Insurance Maps 1885, 1891, 1896, 1902, 1909, 1916, 1925. Filed at the Barker History Center, Austin, Texas.

Webb, Walter Prescott (ed.). <u>Handbook of Texas</u>, 3 vols. Austin: Texas State Historical Association, 1952.

Deed Records, Williamson County Courthouse, Georgetown, Texas.

National Register Nomination for the Round Rock Post Office and William M. Owen House, prepared by Crystal Sasse Ragsdale; on file, Texas Historical Commission, Austin.

### **National Register of Historic Places Inventory—Nomination Form**

For NPS use only received date entered

Continuation sheet

Item number

Page

#### DOWNTOWN HISTORIC DISTRICT LEGAL DESCRIPTION

Beginning at a point being the intersection of the north right-of-way line of East Bagdad Avenue and the east right-of-way line of South Mays Street;

Thence, with the east right-of-way line of South Mays Street in a northwesterly direction in a straight line to the intersection of the east right-of-way line of South Mays Street and the centerline of the alley running parallel to and lying between East Main Street and East Liberty Avenue;

Thence, with the centerline of said alley in a northeasterly direction in a straight line to the intersection of the centerline of said alley and an imaginary north extension of the east property line of Lot number 5, Block 21 of the City of Round Rock;

Thence, with the east property line of Lot number 5, Block 21 of the City of Round Rock and its imaginary extentions in a southeasterly direction in a straight line to the intersection of an imaginary south extension of the said east property line and the south right-of-way line of East Main Street;


Thence, with the south right-of-way line of East Main Street in a southwesterly direction in a straight line to the intersection of the south right-of-way line of East Main Street and the east property line of Lot number 12, Block 10 of the City of Round Rock;

Thence, with the east property line of Lot number 12, Block 10 of the City of Round Rock in a southeasterly direction in a straight line to the intersection of an imaginary south extension of said property line at the centerline of an alley running parallel to, and lying between, East Main Street and East Bagdad Avenue;

Thence, with the centerline of said alley in a southwesterly direction in a straight line to the intersection of the centerline of said alley and an imaginary north extension of the east property line of Lot number 9, Block 9 of the City of Round Rock;

Thence, with the property line of Lot number 9, Block 9 of the City of Round Rock in a southeasterly direction in a straight line to the intersection of said east property line and the north right-of-way line of East Bagdad Avenue;

Thence, with the north right-of-way line of East Bagdad Avenue in a southwesterly direction in a straight line to the intersection of the East right-of-way line of South Mays Street, the Point of Beginning, and containing 4.23 acres of land, more or less.



#### CLASSIFICATION

- CONTRIBUTING BUILDINGS
- D NONCONTRIBUTING BUILDINGS
- --- DISTRICT BOUNDRY

NO SCALE

NO SCALE

NO SCALE

No scale

(formerly International Great Northern Railroad)


Park Service	AND THE RESIDENCE OF THE PARTY
	property and the second control of the secon
Round Rock Commercial Historic District	
Williamson County	
TEXAS	. MAV O IOO
	Working No. MAY 9 198
	Fed. Reg. Date: 2-7-84
	Date Due: 6/9/83 -6/2
	Action: LACCEPTS
resubmission	Entered in the RETURN_
	ernmentNational Register REJECT
owner objection	Federal Agency:
appeal	
Substantive Review: sample	requestappealNR decision
Reviewer's comments:	
	Basem /Cattanta
	Recom. / Criteria
是是一个人,并不是是"EXPERIMENT"的	
	Discipline
	see continuation she
COLUMN TO THE PARTY OF THE PART	e reasons discussed below
1. Name	e reasons discussed below
Charles and the second	e reasons discussed below
1. Name  2. Location	e reasons discussed below
1. Name  2. Location  3. Classification	
1. Name  2. Location	
2. Location  3. Classification  Cotopery Concrete Status Proceed the Patric Acquisition Accessible	
1. Name  2. Location  3. Classification	
2. Location  3. Classification  Cotopery Concrete Status Proceed the Patric Acquisition Accessible	
2. Location  3. Classification  Company Committee Status  Public Acquisition Accounting  4. Owner of Property  5. Location of Legal Description	
2. Location  3. Classification Cottagory Constraint Status Present Use Public Acquisition Accessible  4. Owner of Property  5. Location of Legal Description  6. Representation in Existing Surveys	
2. Location  3. Classification Cottagory Constraint Status Present Use Public Acquisition Accessible  4. Owner of Property  5. Location of Legal Description  6. Representation in Existing Surveys	
2. Location  3. Classification Cottagory Constraint Status Present Use Public Acquisition Accessible  4. Owner of Property  5. Location of Legal Description  6. Representation in Existing Surveys	
2. Location  3. Classification  Company Committee Status Accounts to the Peakle Acquisition Accounts to the Peakle Acquis	
2. Location  3. Classification  Cottagery Constitute Status Present the Prese	
2. Location  3. Classification  Cottagery Constrain Status Present Use Public Acquisition Accessible  4. Owner of Property  5. Location of Legal Description  6. Representation in Existing Surveys  has this property been determ  7. Description  Constituen	
2. Location  3. Classification  Cotopory Concrete Status Proceed the Pedale Acquisition Accessible  4. Owner of Property  5. Location of Legal Description  6. Representation in Existing Surveys    less this property been determined the property been determined to property been det	
2. Location  3. Classification  Correspond Commercial Status  Product Acquisition Accessible  4. Owner of Property  5. Location of Legal Description  6. Representation in Existing Surveys    hear this property been determined by the process and original (If known) physical appearance	
2. Location  3. Classification  Cotopery Concrete Status Present the Public Acquisition Accessible  4. Owner of Property  5. Location of Legal Description  6. Representation in Existing Surveys    has this property been determined by the property by the	
2. Location  3. Classification Cotopery Comercial Status Present Use Public Acquisition Accessible  4. Owner of Property  5. Location of Legal Description  6. Representation in Existing Surveys    host this property been determined   pro	
2. Location  3. Classification  Cotopery Comercial Status Public Acquisition Accessible  4. Owner of Property  5. Location of Legal Description  6. Representation in Existing Surveys    hose this property been determined by the property by the property been determined by the property by the property by the property been determined by the property b	
2. Location  3. Classification  Cotopery Concretip Status Present Use Public Acquisition Accessible  4. Owner of Property  5. Location of Legal Description  6. Representation in Existing Surveys  into this property been determ  7. Description  Condition State one Check one original site original	
2. Location  3. Classification  Codepary Concrete Status Public Acquisition Accessible  4. Owner of Property  5. Location of Legal Description  6. Representation in Existing Surveys  Inter this property been determined the property been determined to pro	

8. Significance						
Period Areas of Significance—Check and justify below						
Specific dates Builder/Architect						
Statement of Significance (in one paragraph)						
summary paragraph						
completeness						
clarity applicable criteria						
justification of areas checked						
relating significance to the resource						
context						
relationship of integrity to significance						
justification of exception						
other						
					•	
9. Major Bibliographical Refere	ences					
10. Geographical Data						
Acresge of nominated property						
Quedrangle name						
URIT References						
Market househow december and househouse		1				
Verbal boundary description and justification		!				
11. Form Prepared By		1.				
THE POINT PROPERTY OF						
12. State Historic Preservation	n Officer Cer	tification				
The evaluated significance of this property within the state is:						
netional state local		*				
State Historic Preservation Officer eigneture						
		*				
13. Other						
Maps						
Photographs						
Other						
Questions concerning this nomin	ation may be	directed	to			
					000	070 050
Signed	Date			Phone:	202	2/2-350

Comments for any item may be continued on an attached sheet



North side of the 100 Block of East Main Street Round Rock, Williamson County, Texas.
Photograph taken December, 1982, by Ruth Parshall.
Negative on file at the Texas Historical Commission.
Oblique view from the southwest.
Photo 1 of 19



North side of the 100 Block of East Main Street Round Rock, Williamson County, Texas. Photograph taken December, 1982, by Ruth Parshall.

Negative on file at the Texas Historical Commission.

Oblique view from the southwest.

Photo 2 of 19



North side of the 100 Block of East Main Street Round Rock, Williamson County, Texas. Photograph taken December, 1982, by Ruth Parshall. Negative on file at the Texas Historical

Negative on file at the Texas Historica Commission.

Oblique view from the southeast.

Photo 3 of 19



Southside of the 100 block of East Main Street Round Rock, Williamson County, Texas. Photograph taken December, 1982 by Ruth Parshall.

Negative filed with the Texas Historical Commission.

Oblique view from the northwest.



The north side of the 200 Block of East Main Street
Round Rock, Williamson County, Texas.
Photograph taken December, 1982, by Ruth Parshall.
Negative on file at the Texas Historical Commission.
Oblique view from the southwest.
Photo 5 of 19



Miller's Exchange Bank, 103 East Main Street Round Rock, Williamson County, Texas. Photograph taken November, 1982, by Ruth Parshall.

Negative on file at the Texas Historical Commission.

North (front) elevation.

Photo 6 of 19
Site #2



Sam Bass General Store, 105 E. Main Street Round Rock, Williamson County, Texas. Photograph taken November, 1982, by Ruth Parshall.

Negative on file at the Texas Historical Commission.
North (front) elevation.

Photo 7 of 19 Site #3



The Fair, 117 East Main Street
Round Rock, Williamson County, Texas.
Photograph taken November, 1982, by Ruth
Parshall.
Negative on file at the Texas Historical
Commission.
North (front) elevation.
Photo 8 of 19
Site #8



Shuey's Furniture Store, 100 East Main Street
Round Rock, Williamson County, Texas.
Photograph taken, November, 1982, by Ruth
Parshall.
Negative on file at the Texas Historical
Commission.
South (front) elevation.

Photo 9 of 19 Site #11



Otto Reinke Building, 102 East Main Street Round Rock, Williamson County, Texas. Photograph taken November, 1982, by Ruth Parshall.

Negative on file at the Texas Historical Commission.


South (front) elevation.

Photo 10 of 19

Site #12



Round Rock Insurance and John's Barber Shop,
104 East Main Street
Round Rock, Williamson County, Texas.
Photograph taken November, 1982, by Ruth
Parshall.
Negative on file at the Texas Historical
Commission.
South (front) elevation.
Photo 11 of 19
Site #13



Round Rock Leader, 112 East Main Street
Round Rock, Williamson County, Texas.
Photograph taken November, 1982, by Ruth
Parshall.
Negative on file at the Texas Historical
Commission.
South (front) elevation.
Photo 12 of 19
Site #16

Round Rock Leader

Round Rock Leader, 112 East Main Street
Round Rock, Williamson County, Texas.
Photograph taken November, 1982, by Ruth
Parshall.
Negative on file at the Texas Historical
Commission.
South (front) elevation.
Photo 13 of 19
Site #16

VATIONA B-A First National Bank, 118 East Main Street
Round Rock, Williamson County, Texas.
Photograph taken November, 1982, by Ruth
Parshall.
Negative on file at the Texas Historical
Commission.
South (front) elevation.

Photo 14 of 19
Site #19




Economy Drug Store, 204 East Main Street Round Rock, Williamson County, Texas.
Photograph taken November, 1982, by Ruth Parshall.
Negative on file at the Texas Historical Commission.
South (front) elevation.
Photo 15 of 19

Site #21



Dr. Gregg's Office, 206 East Main Street
Round Rock, Williamson County, Texas.
Photograph taken November, 1982, by Ruth
Parshall.
Negative on file at the Texas Historical
Commission.
South (front) elevation.

Photo 16 of 19 Site #22



Nelson Hardware, 203 East Main Street Round Rock, Williamson County, Texas. Photograph taken December, 1982, by Ruth Parshall. Negative on file at the Texas Historical Commission. Oblique view from the northwest.


Photo 17 of 19 Site #24



Nelson Hardware, 203 East Main Street
Round Rock, Williamson County, Texas.
Photograph taken November, 1982, by Ruth
Parshall.
Negative on file at the Texas Historical
Commission.
North (front) elevation.

Photo 18 of 19 Site #24

24



Old Post Office Building, 107 South Mays Street Round Rock, Williamson County, Texas.
Photograph taken November, 1982, by Ruth Parshall.
Negative on file at the Texas Historical Commission.
West (front) elevation.
Photo 19 of 19
Site #25