National Register of Historic Places Inventory—Nomination Form

For NPS use only
received III | A per
date entered

Continuation sheet

Item number

A11

Page 48

22. Name: Kone-Cliett House

Location: 724 Burleson Street

Classification: Category - building; Ownership - private; Status - occupied;

Accesible - yes, restricted; Present use - private residence.

Owner of property: Mrs. Azlete R. Little

100 Algarita

San Marcos, Texas 78666

Description: Condition - good; Altered; Original site.

Judge Ed Kone built his two-story frame house on the bluff overlooking the town. Like many of its period, the structure has an asymmetrical plan, with a double gallery curving from the bevelled-corner ell around to the side wall. A corrugated, metal, pyramidal roof with cross gables to the southeast, southwest, and northeast covers the main portion of the house, which is supported by a cedar-post foundation skirted with pressed metal.

Ornament is restrained but elegant. Both porch levels are framed by turned posts with sawn brackets, have beaded-board "friezes" under the eaves, have beaded ceilings, and are edged with spindle rails. Floors and steps are wood, with turned newels. Once the steps curved outward, but they were replaced incorrectly. Also, a few of the brackets fell off, but are in storage awaiting repair. Similar sawn brackets fill in the gable ends. Doors onto the porch on both levels are original.

Some of the sash windows with one-over-one lights are extra wide. The den, at the rear, contains nine-pane windows. Major doors have transoms.

The centerpiece for the interior is a double stair that converges from the front entry and rear den to a common landing. Each stair is in several different sections, creating an interesting interplay of planes, and is decorated with beading and carved newels. Beading is used liberally for walls and ceilings. Bullseye moldings are common in the front part of the house, plain frames in the back. A built-in gun rack is a feature upstairs.

Modern stained glass fills two transoms, two closets have been added, a bathroom was modernized, and a second-floor, rear porch was filled in. The kitchen has been slightly updated, but the old cabinets and high ceilings keep it strongly in character with the Victorian period. The present owners have begun a renovation program that will correct the surficial alterations.

National Register of Historic Places Inventory—Nomination Form

For NPS use only received date entered

Continuation sheet

Item number

A11

Page 49

Fortunately, several outbuildings have survived, and should be considered as contributing to the property. They are (1) a saltbox-shaped, board-and-batten servants' quarters, with V-crimp metal roof and inset porch; (2) a well house with a diagonally laid, V-crimp roof and scalloped eyelet trim under the eaves; (3) a board-and-batten garage with hipped roof; (4) a board-and-batten stable with corrugated metal roof and concrete floor; (5) and a three-holer outhouse. The structures are near the front of the lot, which reaches deep into a wooded area.

Significance: Period - 1800-1899, 1900-; Areas of significance - architecture, law. Specific dates - 1890, 1902.

Among the fine homes built on the bluff created by the Balcones Fault is the Kone-Cliett House, rebuilt in 1902 in a design held over from the Victorian period. Hall-marks of its style are the lavish interior details, asymmetrical plan, and airy double porch. Among the first owner's accomplishments were his roles as County Judge and State Commissioner of Agriculture.

Edward R. Kone (born 1848) came with his family from Montgomery, Alabama, to Stringtown, Hays County, in 1851. He worked as a store clerk and cattle driver before studying law at Coronal Institute. Before he was 21 years old or licensed to practice, Kone had been appointed county attorney. During Reconstruction he briefly served as sheriff. In 1872, he married Lucinda Martin, who gave him four daughters. While County Judge, a position he filled from 1878 to 1890, and from 1894 to 1908, he and his wife acquired the subject property in 1881. They built their first home here, probably in 1890. In 1896, he became Hays County's first superintendant of education. Also during this period he served for two years as a special district judge.

January 18, 1902, at least part of the Kone House burned, as irony would have it, while a firemen's benefit party was in full swing across town. Research has not revealed how much of the house burned, and it was not mentioned in a list of well-remembered fires. Perhaps only the rear had to be rebuilt. At any rate, the Kones did rebuild immediately and remained on the property for several years more.

Gov. T.M. Campbell appointed Kone Commissioner of Agriculture in 1908. From 1920 until his death in 1933 Kone was Corporation Judge for the City of Austin, where he had lived since about 1911.

The property passed in 1914 to Oran W. Cliett, owner and operator of Cliett Cotton Breeding Farms and, after 1933, postmaster. The present owner's family acquired it in 1956.

National Register of Historic Places Inventory—Nomination Form

For NPS use only received date entered

Continuation sheet

Item number

A11

Page 50

Bibliography:

Handbook of Texas, vol. 1.
Interview with Azalete Little, April 13, 1982.
Deed of Trust, dated June 25, 1958.
San Marcos Record, February 3, 1933, and March 17, 1922.
Frances Stovall, Unpublished notes on Ed R. Kone, August 1, 1982. On file at San Marcos Public Library.

Geographical data: Acreage - Approximately two acres.

UTM reference - 14 / 601340 / 3305870

Verbal Boundary Description - The nominated property is "D" lot of Farm Lot 15 of the Original Town Site, and can be more accurately described as two rectangles joined together. The first rectangle measures 130 ft. along Burleson, from the north corner of Burleson and Browne Streets, and 431.9 ft. along Browne, from the same corner. The second rectangle is adjacent to the first and measures 104.4 feet southwest to northeast, or against the rear line of the first rectangle, and 66.67 ft. along Browne Street.

WASO Form - 177 ("R" June 1984)


UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES EVALUATION/RETURN SHEET

Kone-Cliett House (San Marcos MRA)					
Hays County					
TEXAS	Working No. <u>7-/4-83</u>				
	Working No/				
	Fed. Reg. Date: Date Due: 8/11/83 - 8/28/83				
	A				
resubmission	Action: ACCEPT 8/26/83				
nomination by person or local government	REJECT				
owner objection	Federal Agency:				
appeal					
Substantive Review: sample request appeal	☐ NR decision				
Reviewer's comments:					
	Recom./Criteria				
	Reviewer				
	Discipline				
	Date see continuation sheet				
	see continuation sneet				
Nomination returned for:technical corrections cited belowsubstantive reasons discussed below	Taguis, los comos especiales de la comos especiales de la comos de				
1. Name	man et alle tallet was morte and action of the leaf of				
2. Location					
3. Classification					
Category Ownership Status Public Acquisition Accessible	Present Use				
4. Owner of Property					
5. Location of Legal Description					
6. Representation in Existing Surveys	er ende grenerations de Forder III au				
Has this property been determined eligible? ☐ yes ☐ no	a b				
7. Description					
Condition Check one	Check one				
excellent deteriorated unaltered	original site				
good ruins altered	moved date				
☐ fair ☐ unexposed					
Describe the present and original (if known) physical appearance					
summary paragraph					
completeness					
□ clarity					
☐ alterations/integrity					
dates					
boundary selection					

8. Significance	THE STATE OF THE S
Period Areas of Significance—Check and justify below	
Specific dates Builder/Architect	
Statement of Significance (in one paragraph)	
	Kone-Clett Loure (San Marraca MRA)
summary paragraph completeness	Hays Couety TEXAS
□ clarity	CA ALL
applicable criteria	
☐ justification of areas checked ☐ relating significance to the resource	
context	
relationship of integrity to significance	
☐ justification of exception ☐ other	
9. Major Bibliographical References	
10. Geographical Data	
Acreage of nominated property	
Quadrangle name	
UTM References	and the second of the second o
Verbal boundary description and justification	
11. Form Prepared By	And the Control of th
12. State Historic Preservation Officer Certification	A CONTRACTOR OF THE PROPERTY O
The evaluated significance of this property within the state is:	
national state lead	
national state local	
State Historic Preservation Officer signature	A VIII DESCRIPTION TO A STREET AND A STREET
atala dasa	
title date	
13. Other	
Maps Property nomination and indicated of	
- I i i cogi a pi i i	, , , ,
Other	But One Live
Questions concerning this possination may be discorded	
Questions concerning this nomination may be directed to	
-6.	
Signed Milwert Byers Date	8/26/83 Phone:
Signed Date	rnone:

National Register of Historic Places Inventory—Nomination Form



Continuation sheet

Item number

A11

Page 48

22. Name: Kone-Cliett House

Location: 724 Burleson Street

Classification: Category - building; Ownership - private; Status - occupied;

Accesible - yes, restricted; Present use - private residence.

Owner of property: Mrs. Azlete R. Little

100 Algarita

San Marcos, Texas 78666

Description: Condition - good; Altered; Original site.

Judge Ed Kone built his two-story frame house on the bluff overlooking the town. Like many of its period, the structure has an asymmetrical plan, with a double gallery curving from the bevelled-corner ell around to the side wall. A corrugated, metal, pyramidal roof with cross gables to the southeast, southwest, and northeast covers the main portion of the house, which is supported by a cedar-post foundation skirted with pressed metal.

Ornament is restrained but elegant. Both porch levels are framed by turned posts with sawn brackets, have beaded-board "friezes" under the eaves, have beaded ceilings, and are edged with spindle rails. Floors and steps are wood, with turned newels. Once the steps curved outward, but they were replaced incorrectly. Also, a few of the brackets fell off, but are in storage awaiting repair. Similar sawn brackets fill in the gable ends. Doors onto the porch on both levels are original.

Some of the sash windows with one-over-one lights are extra wide. The den, at the rear, contains nine-pane windows. Major doors have transoms.

The centerpiece for the interior is a double stair that converges from the front entry and rear den to a common landing. Each stair is in several different sections, creating an interesting interplay of planes, and is decorated with beading and carved newels. Beading is used liberally for walls and ceilings. Bullseye moldings are common in the front part of the house, plain frames in the back. A built-in gun rack is a feature upstairs.

Modern stained glass fills two transoms, two closets have been added, a bathroom was modernized, and a second-floor, rear porch was filled in. The kitchen has been slightly updated, but the old cabinets and high ceilings keep it strongly in character with the Victorian period. The present owners have begun a renovation program that will correct the surficial alterations.

National Register of Historic Places Inventory—Nomination Form

For NPS use only
received JUL 1 Å 1983
date entered

Continuation sheet

Item number

A11

Page 49

Fortunately, several outbuildings have survived, and should be considered as contributing to the property. They are (1) a saltbox-shaped, board-and-batten servants' quarters, with V-crimp metal roof and inset porch; (2) a well house with a diagonally laid, V-crimp roof and scalloped eyelet trim under the eaves; (3) a board-and-batten garage with hipped roof; (4) a board-and-batten stable with corrugated metal roof and concrete floor; (5) and a three-holer outhouse. The structures are near the front of the lot, which reaches deep into a wooded area.

Significance: Period - 1800-1899, 1900-; Areas of significance - architecture, law. Specific dates - 1890, 1902.

Among the fine homes built on the bluff created by the Balcones Fault is the Kone-Cliett House, rebuilt in 1902 in a design held over from the Victorian period. Hall-marks of its style are the lavish interior details, asymmetrical plan, and airy double porch. Among the first owner's accomplishments were his roles as County Judge and State Commissioner of Agriculture.

Edward R. Kone (born 1848) came with his family from Montgomery, Alabama, to Stringtown, Hays County, in 1851. He worked as a store clerk and cattle driver before studying law at Coronal Institute. Before he was 21 years old or licensed to practice, Kone had been appointed county attorney. During Reconstruction he briefly served as sheriff. In 1872, he married Lucinda Martin, who gave him four daughters. While County Judge, a position he filled from 1878 to 1890, and from 1894 to 1908, he and his wife acquired the subject property in 1881. They built their first home here, probably in 1890. In 1896, he became Hays County's first superintendant of education. Also during this period he served for two years as a special district judge.

January 18, 1902, at least part of the Kone House burned, as irony would have it, while a firemen's benefit party was in full swing across town. Research has not revealed how much of the house burned, and it was not mentioned in a list of well-remembered fires. Perhaps only the rear had to be rebuilt. At any rate, the Kones did rebuild immediately and remained on the property for several years more.

Gov. T.M. Campbell appointed Kone Commissioner of Agriculture in 1908. From 1920 until his death in 1933 Kone was Corporation Judge for the City of Austin, where he had lived since about 1911.

The property passed in 1914 to Oran W. Cliett, owner and operator of Cliett Cotton Breeding Farms and, after 1933, postmaster. The present owner's family acquired it in 1956.

San Marcos Public Library.

National Register of Historic Places Inventory—Nomination Form

For NPS use only
received ALL 1.4 1997
date entered

Continuation sheet

Item number

A11

Page 50

Bibliography:

Handbook of Texas, vol. 1.

Interview with Azalete Little, April 13, 1982.

Deed of Trust, dated June 25, 1958.

San Marcos Record, February 3, 1933, and March 17, 1922.

Frances Stovall, Unpublished notes on Ed R. Kone, August 1, 1982. On file at

Geographical data: Acreage - Approximately two acres.

UTM reference - 14 / 601340 / 3305870

Verbal Boundary Description - The nominated property is "D" lot of Farm Lot 15 of the Original Town Site, and can be more accurately described as two rectangles joined together. The first rectangle measures 130 ft. along Burleson, from the north corner of Burleson and Browne Streets, and 431.9 ft. along Browne, from the same corner. The second rectangle is adjacent to the first and measures 104.4 feet southwest to northeast, or against the rear line of the first rectangle, and 66.67 ft. along Browne Street.

WASO Form - 177 ("R" June 1984)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES EVALUATION/RETURN SHEET

Kone-Cliett House (San Marcos MRA)	
Hays County	
TEXAS	- 162
	Working No. 7.14.83
	Fed. Reg. Date:
	Date Due: 2/10/37, Action: ACCEPT 2/1/83 red in the RETURN
	Action:ACCEPT/2///80
resubmission	onal Register RETURN
	Onal REJECT
owner objection	Federal Agency:
appeal	
Substantive Review: sample request appeal	☐ NR decision
Reviewer's comments:	
	Recom./Criteria
	Reviewer
	Discipline
	Date
	see continuation sheet
Nomination returned for:technical corrections cited belowsubstantive reasons discussed below	
1. Name	a probablica de la lacción de la contraction de la probablica de la contraction de l
2. Location	
3. Classification	
	· 自己自己的自己的自己的自己的自己的自己的自己的自己的自己的自己的自己的自己的自己
Category Ownership Status Public Acquisition Accessible	Present Use
4. Owner of Property	Section 1997 And the section of the
5. Location of Legal Description	
6. Representation in Existing Surveys	
Has this property been determined eligible?	
7. Description	
Condition Check one	Check one
excellent deteriorated unaltered	original site
excellent deteriorated unaltered	original site
good ruins altered	original site moved date
good ruins altered fair unexposed	
good ruins altered	
good ruins altered fair unexposed Describe the present and original (if known) physical appearance	
good ruins altered fair unexposed Describe the present and original (if known) physical appearance summary paragraph	
good ruins altered fair unexposed Describe the present and original (if known) physical appearance summary paragraph completeness	
good ruins altered fair unexposed Describe the present and original (if known) physical appearance summary paragraph completeness clarity	
good ruins altered fair unexposed Describe the present and original (if known) physical appearance summary paragraph completeness clarity alterations/integrity	
good ruins altered fair unexposed Describe the present and original (if known) physical appearance summary paragraph completeness clarity	

8. Significance		and the state of t	
Period Areas of Significance—Check and justify be	low		
Specific dates Builder/Architect Statement of Significance (in one paragraph)			
summary paragraph completeness clarity applicable criteria			
☐ justification of areas checked ☐ relating significance to the resource ☐ context ☐ relationship of integrity to significance			
☐ justification of exception ☐ other			
9. Major Bibliographical References			
10. Geographical Data			
Acreage of nominated property Quadrangle name UTM References		ing the state of t	
Verbal boundary description and justification			
11. Form Prepared By			
12. State Historic Preservation Officer Certification The evaluated significance of this property within the s	state is:	in Observed	
nationalstatel	ocal		
State Historic Preservation Officer signature			
title date			
13. Other			
☐ Maps ☐ Photographs ☐ Other			
Questions concerning this nomination may be directed	to		
Signed	Date	Ph	one:




Photo by Lissa Anderson, July, 1982. Negative property of HASM, on file at SMPL.

East oblique, camera facing west. Photo 90 of 150.



Photo by Lissa Anderson, July, 1982. Negative property of HASM, on file at SMPL.

East oblique of southeast facade, camera facing west.
Photo 91 of 150.



Photo by Lissa Anderson, May, 1982. Negative property of HASM, on file at SMPL.

Interior, detail of stair. Photo 92 of 150.




Photo by Lissa Anderson, May, 1982. Negative property of HASM, on file at SMPL.

East oblique of servants' quarters and well-house, camera facing west.
Photo 93 of 150.

Please refer to the map in the Multiple Property Cover Sheet for this property

Multiple Property Cover Sheet Reference Number: _____64000853