NPS Form 10-900-a OMB No. 1024-0018 (3-82) Exp. 10-31-84 **United States Department of the Interior** National Park Service For NPS use only **National Register of Historic Places** received **Inventory**—Nomination Form date entered Continuation sheet A11 Page 71 Item number 31. Name: Williams-Tarbutton House (Common names - Dr. Wilburn Williams House, Tarbutton House Location: 626 Lindsey Street Classification: Category - building; Ownership - private; Status - occupied;

Owner of property: Mrs. Myrtle Penn Williams Tarbutton 626 Lindsey Street San Marcos, Texas 78666

Description: Condition - good; Altered; Original site.

Nestled in an oak grove on a hillside is the Williams-Tarbutton House, an important Prairie-style home. Two stories plus basement, red brick walls, low hipped roof of green-painted standing-seam metal, broad overhanging eaves, and irregular plan are the basic characteristics of the house.

Accessible - yes, restricted; Present use - private residence.

The house faces Lindsey Street. On that side occurs the main extension from the house block. Here four massive, rectangular piers define the large first-floor porch which has been screened. The porch openings rest on a broad concrete stringcourse that is also found under the second-floor windows. Small brick piers below the stringcourse add a touch of detail. Set back from the porch on the second floor is a section enclosed by 8-by-8 casement windows.

The long axis runs along Roger Street. On that side, the eaves of the hip-roofed porte-cochere and first-floor kitchen wing add horizontal emphasis. A rectangular bay distinguishes the Scott Street side. Three first-floor windows are double hung. All are on thick, white, concrete sills. The stained-glass panels that flank the fireplace replace plain glass.

There are several attractive interior features, such as pocket French doors between the entry and living room and dining room, low arches, built-in bookcases, and ceiling moldings. Progressive innovations include a laundry chute, a cedar closet, linen closet, and central vacuum system. Interior spaces are large and airy, in keeping with the exterior style.

The only major alteration was a 1948 extension of the kitchen. Glass bricks and casements indicate the newer section. Since the addition merely elarged a pre-existing block, no real, adverse effect was made. The porch was screened at the same time. Carpeting was laid over the oak floors.

NPS Form 10-900-a (3-82)		OMB No. 1024-0018 Exp. 10-31-84
United States Department National Park Service	For NPS use only	
National Register Inventory—Nomin	received date entered	
Continuation sheet	Item number A11	Page 72
	the property there is a reddish-o infill, are shaded by large oak to	

property and a matching garage envisioned by Ayres were not built because of a cost

Significance: Period - 1900- ; Areas of significance - achitecture, other (medicine); Specific dates - 1912-1914. Atlee B. Ayres, architect, Oscar Davis, mason.

The Prairie Style was never as popular in Texas as it was further north. Therefore, a clearly defined example of the style is inherently significant. Will Martindale's house, designed by Atlee B. Ayres with strong horizontal lines, overhanging eaves, and geometric forms, is such an example. Dr. Wilburn Williams, a long-time San Marcos physician, lent the house additional historical importance.

W.W. Martindale, a prosperous local farmer, began construction in 1912. A prominent San Antonio architect had drawn the plans; San Marcos resident Oscar Davis did most of the brick and rock work. The original cost estimate was \$12,000, but by the time the house was finished in 1914 it had increased to about \$15,000. At the time of completion, the house must have seemed a marvel of modernity. The sleek lines and open spaces still contrast dramatically with the late-Victorian structures that were then the norm. Built-in conveniences such as the cedar closet and vacuum system made life easier.

In 1930, Dr. Wilburn Williams bought the house and the Martindales moved to the former Williams home. Dr. Williams practiced medicine in town for 42 years. He and his wife Myrtle operated a private hospital, the San Marcos Sanitarium, on the corner of Bishop and Belvin from 1912 to 1919.

The Williams' daughter Myrtle inherited the house, and she and her husband now reside there.

Bibliography:

overrun.

Tula Townsend Wyatt, "A History of Memorial Hospital," c. 1938, unpublished. On file at the San Marcos Public Library.

Interview with Frances Stovall, July 8, 1982. Interview with Myrtle Penn Williams Tarbutton and Ed Tarbutton, April 29, 1982. Interview of Myrtle Tarbutton by Gwen Smith, undated.

Geographical data: Acreage - approximately one acre. UTM reference - G 14 / 601330 / 3306060

Verbal Boundary Description - C.L. McGehee Addition, Block 4, Lots 3 and 4.

WASO Form - 177 ("R" June 1984)

#### UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

### NATIONAL REGISTER OF HISTORIC PLACES EVALUATION/RETURN SHEET

Williams-Tarbutt	ton House (San Marcos M	RA)	
Hays County			
TEXAS			1-111.02
			Working No
			Fed. Reg. Date: 2.7.84 Date Due: 8/11/83 - 8/28/83
			Action:
resubmission	a ar local coverament	Enter	ed in theREJECT
owner objection	n or local government	Natio	nal Register
appeal			nal Registagency:
Substantive Review:	sample reques	t 🗌 appeal	NR decision
Reviewer's comments:			
			Recom./Criteria
			Reviewer
			Discipline
			Date
			see continuation sheet
Nomination returned for:	technical corrections cite    substantive reasons discu		
1. Name			
2. Location			
3. Classification	and a supervised of the second second	an en an	
Category	Ownership Public Acquisition	Status Accessible	Present Use
4. Owner of Property			an an ann an suite an ann an suite an ann an
5. Location of Legal Des	cription	Π. <sup>2</sup>	No
6. Representation in Exis	sting Surveys		in the state of the second state of the
Has this property been de	termined eligible? 🛛 🗍 yes	🗆 no	
7. Description		And the second second	the second s
Condition		Check one	Check one
excellent	deteriorated	unaltered	original site
good		altered	moved date
🗖 fair	unexposed		
Describe the present and	original (if known) physical appe	arance	
summary paragraph			
Clarity			
alterations/integrity			
dates			
boundary selection			

## 8. Significance

Period	Areas of	Significance-	-Check and	justify	y below
--------	----------	---------------	------------	---------	---------

Specific dates Builder/Architect Statement of Significance (in one paragraph)

summary paragraph
completeness
clarity
applicable criteria
justification of areas checked
relating significance to the resource
context
relationship of integrity to significance
justification of exception
other

#### 9. Major Bibliographical References

10. Geo	graphi	ical I	Data
---------	--------	--------	------


Acreage of nominated property	
Quadrangle name	
UTM References	

Verbal boundary description and justification

## 11. Form Prepared By

12. State Historic Preserva		A Street	A Mail and Asian in	
The evaluated significance	of this property within the state	IS:		
national	statelocal			
State Historic Preservation	Officer signature			
title	date			
13. Other				
<ul> <li>Maps</li> <li>Photographs</li> <li>Other</li> </ul>				
Questions concerning this	nomination may be directed to _			<u>an dire di</u>
Signed		Date	Phone:	ng (Vit, Color Ang (Color Spin) (Color Spin)

Comments for any item may be continued on an attached sheet



Historic Resources of San Marcos San Marcos, Hays County, Texas #31. Williams-Tarbutton House

Drawing by Atlee Ayres, courtesy of the owner. Copy photo by Sally S. Victor, negative property of HASM, on file at SMPL.

South oblique, facing north. Photo 124 of 150.



Historic Resources of San Marcos San Marcos, Hays County, Texas #31. Williams-Tarbutton House

Photo by Lissa Anderson, January, 1983. Negative property of HASM, on file at SMPL.

South oblique, camera facing north. Photo 125 of 150.



Historic Resources of San Marcos San Marcos, Hays County, Texas Williams-Tarbutton House #31.

Photo by Lissa Anderson, July, 1982. Negative property of HASM, on file at SMPL.

Southeast facade, camera facing northwest. Photo 126 of 150.



Historic Resources of San Marcos San Marcos, Hays County, Texas #31. Williams-Tarbutton House

Photo by Lissa Anderson, July, 1982. Negative property of HASM, on file at SMPL.

North oblique, camera facing south. Photo 127 of 150.

# Please refer to the map in the Multiple Property Cover Sheet for this property

Multiple Property Cover Sheet Reference Number: 64000853