
## **United States Department of the Interior National Park Service**

## National Register of Historic Places Inventory—Nomination Form



Continuation sheet Item number all Page 122

	6.USGS Quad No. 2897-441Site No. I-223
Historic Sites Inventory (Adapted from THC HSI Form, 10-83)	7.UTM Sector No. 694–3187
	8. Date: Factual Est c. 1910
1. Randall Building 2. 103-05 W. Santa Rosa	9. Architect/Builder N/A
4. Address P.O. Box 1159, Victoria 77901	ont.) Contractor
5. Legal Description OTS Blk. 112 N. ½ Lot	
	ernacular 13.No. stories E. half-l story
	ood floor & roof systems & built-up tar & grave
15. Plan rectangular-open plan	
17.Roof/cornice details raised brick parap	et; denticulated brick cornice
18. Chimneys	
19.Windows wood sash fixed display window	ws on 1st floor; 6/6 w/ transoms on 2nd floor
20.Entrances recessed double doors in each	th half of the building
21. Porches canopy suspended on N. elev.	
22. Architectural details/misc. features inc	clude 2 sets of 3 bays defined by brick panels
and window arrangement; western-most bay	has single-door entry to 2nd floor;
denticulated brick cornice.	
23.Interior details	
24. Associated outbldgs./structures	
25. Present condition fair	
26. Significance : ARCHITECTURE, COMMERCE.	Victoria contracting company Bailey Mills
	to honor Mrs. L.B. Randall of San Antonio. The
	their meeting hall. The first floor housed
	portion of the building housed the Victoria
Hardware Company and then auto supply stor	
northware company and enem added supply seed	too for many years.
27. Context: Moved Date or orig	inal site x 28. Area description CBD
27. Context: MovedDateor orig	mai site X 20. Area description CBD
29. Bibliography City directories; Sanborn	34. YEAR DRWR ROLL FRME ROLL FRME
maps1907 & 1912	THC 31 7 to 9
30.Informant(s)	to to
50. Illior mail(s)	Photos: 35.Slides
21 Designations, HARS (no )TEV	
31. Designations: HABS (no.)TEX-	
RTHL; File name	
NR; File name	37.Other
32.Other UTM: 14/694560/3187060  33.Recorder DH/Hardy Heck Moore Date 19	

## **United States Department of the Interior National Park Service**

# National Register of Historic Places Inventory—Nomination Form

For NPS use only
received AUG 1 | 1986
date entered

Continuation sheet

Item number all

Page 123

	#3-4	Kath	erina	Н	mel a	d )	Marht	2 6	Man	tin	926	M+	Pair	ior	San	
	113-4.	Racin	Anto	nio.	Texas	2	78213	ia S.	Hai	LIII	920	116.	Nall	ITEL.	Sall	40.00
4			micc	,,,,	TCAG		70213	•			-					
				1			1 376					1		1/2		
The state of		37 / T	1					1000	18 4				120			A TO STATE
					1-45										6	
			18				91.321	100						- 4.1.4		
			1									Trave.	Inc. P			
														100		
										Pall			174	97.8		
				las u				1914							96.00	WALL T
100	EX											West of the second				
		1										ALC:				
	BEST							21, 11			a la	3211	0			F 5
							100							19		1 4 20 2
AC 10223975				19675						W. L. C.	Tige	1, W 12		100		
	-				-									July -	10-2-	
			10.23					2561	316.4			D.V.			1 9.7	102
	-				-	- 4		111111111111111111111111111111111111111	2010						-	
					1- 200	4								17-12		Fig. 1
		766					1									
A COL														Ser		(A) (A) (A)
								++++	111	+ + + +	11					+
																1
			-									1	-			
						F-47.1	1		100					1111		
															1	
			-						111			111			1	
							++++		-		+++	111			++++	
									1	-						
								++++			11:			1	-	
						_	155				-		-	1111		
														* * * * 1		
										-+	+++		-			
								-	-	-					-	
										-						
			-				-						-		-	
						-	-		-			-	-		-	
		AND PROPERTY.				-										
									-	-			-			

WASO Form - 177 ("R" June 1984)

### UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

#### NATIONAL REGISTER OF HISTORIC PLACES EVALUATION/RETURN SHEET

Randall Building	(Victoria MRA)		
Victoria County			ALIC L. F. 1000
TEXAS			Working No. AUG 1 1 1986
			Fed. Reg. Date:
			Date Due: 9/4/86 - 9/25/86
			Action:ACCEPT
resubmission			
	on or local government		REJECT
owner objection	on or local government		
appeal			Federal Agency:
- appear			
Substantive Review:	sample reque	st appeal	☐ NR decision
Reviewer's comments:			
			Recom./Criteria
			Reviewer
			Discipline
			Date
			see continuation sheet
Nomination returned for	technical corrections cite	ed below	- 4 The Hollowen and have
Trommuton retained for	substantive reasons discu		
1. Name			the state of the s
2. Location			
3. Classification			
Category	Ownership Public Acquisition	Status Accessible	Present Use
4. Owner of Property		The state of the s	e a minute est employed a destination of a territories of the
5. Location of Legal Des	scription	470	
6. Representation in Ex	isting Surveys		The second section of the second second second
Has this property been d	etermined eligible?	no	
7. Description			
Condition		Check one	Check one
	deteriorated	unaltered	original site
excellent	ruins	altered	moved date
good		artered	moved date
fair	unexposed		
Describe the present and	original (if known) physical app	earance	
summary paragraph			
completeness			
☐ clarity			
☐ alterations/integrity			
dates			
boundary selection			

8. Significance	
Period Areas of Significance—Check and justify below	TAM S
Specific dates  Statement of Significance (in one paragraph)	
summary paragraph completeness clarity applicable criteria justification of areas checked relating significance to the resource context	Randall Pullding (Victoria MRA). Victoria County TRICKS
relationship of integrity to significance justification of exception other	
9. Major Bibliographical References	
Acreage of nominated property  Quadrangle name  UTM References	The contract of the contract o
Verbal boundary description and justification	Promise 3
11. Form Prepared By	Cals Holder
12. State Historic Preservation Officer Certification The evaluated significance of this property within the state is:	
national state local	
State Historic Preservation Officer signature	
title date	
13. Other	Conduitne
☐ Maps ☐ Photographs ☐ Other	
Questions concerning this nomination may be directed to	Constitution of the place of the property of the party of
Signed	Phone:

## **United States Department of the Interior National Park Service**

## National Register of Historic Places Inventory—Nomination Form

For NPS use only received 8/11/86 date entered

Continuation sheet

Item number

Page

Multiple Resource Area Thematic Group

State	TEXAS			
	ination/Type of Review			Date/Signature
	Proctor House	National Register	Keeper	Alous Byan 121
		0		
			Attest	1./11 - R R. 014
82.	ProctorVandenberge House	Substantive Review	Keeper	William D. Dusbry
		0	Attest	Bruce J. noble, p. 12/8
83.	Randall Building	Entered in the	Keeper	Selvers Byer 12/4
			Attest	
84.	Regan, D.H., House	Substantive Resident	Keeper	William B. Bush
		$\mathcal{U}$	Attest	Bruce & noble p. 12/81
35.	Schroeder House	National Register	Keeper	Selove Byen 12/
			Attest	
36.	Sigmund House	Substantive Review	Keeper	William B. Brushi
			Attest	Bruce J. Moble, p. 12/
37.	Southern Pacific RR	Substantive Neview 4	Determi Keeper	ned Eligible Bushin
	Cuadaluna Bridge	OWNER OBJECT	ION	Para Mill o 12 18
			Attest	Bruce g. Noble, Jr. 12/9
38.	South Bridge Street Historic District	dubatentira resta	Keeper	auch Palville Andles 9/
	mistoric bistrict	0	Attest	
39.	C	Entered in the	Keeper	Alores Byen 12/3
			Attest	
90.	TownsendWilkins House	Substantive Feel	Keeper	William B- Bushi
			Attest	Aruse O Moble a 121

### UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

#### NATIONAL REGISTER OF HISTORIC PLACES EVALUATION/RETURN SHEET

Randall Building (Victoria MRA)		the state of the s
Victoria County		Working No. 8/11/86
TEXAS		Fed. Reg. Date: 2/2/88
		Date Due: 19/19/86
./		Action: LACCEPT 12-9-86
resubmission	Entered in the	RETURN
nomination by person or local government	National Regist	REJECT
owner objection		Federal Agency:
appeal		
Substantive Review: sample request	appeal	☐ NR decision
Reviewer's comments:		
		Recom./Criteria
		Reviewer
		Discipline
		Date
		see continuation sheet
Nomination returned for:technical corrections cited belosubstantive reasons discussed be		
1. Name		Control (Control Control Contr
2. Location		
3. Classification		
Category Ownership Public Acquisition	Status Accessible	Present Use
4. Owner of Property	or an areas by 22,000	r i decent al antique per l'action de la company de de la c
5. Location of Legal Description	5.00	Sittle of formula
6. Representation in Existing Surveys		The section of the part through a contract
Has this property been determined eligible?	□ no	
7. Description		
Condition	k one	Check one
excellent deteriorated u	unaltered	original site
	ltered	moved date
ar and an area area area area area area area a		
Describe the present and original (if known) physical appearance		
summary paragraph		
completeness		
clarity		
alterations/integrity		
dates boundary selection		
boundary selection		

8. Signifi	cance	THE STREET SHAPE ON TO		Part (1986) and (1971)
Period	Areas of Significance—Check and justi	fy below		
Specific o	dates Builder/Archi	tect		
	t of Significance (in one paragraph)			
	nary paragraph		(Am' of-master	) and the tiple (
☐ comp				Victoria Tounty
applic	cable criteria			
	cation of areas checked ng significance to the resource			
conte				
	onship of integrity to significance			
other	cation of exception			
	· · · · · · · · · · · · · · · · · · ·			
9. Major	Bibliographical References			
10. Geo	graphical Data	1000		
Acreage (	of nominated property			
Quadran	gle name			
UTM Re	ferences			
Verbal b	oundary description and justification			
11. For	n Prepared By			
	Historic Preservation Officer Certificati			
The eval	uated significance of this property within	the state is:		
	national state	local		
State His	toric Preservation Officer signature			
title	date			
13. Oth	er			
☐ Maps				
☐ Phot	ographs			
☐ Othe				
Question	s concerning this nomination may be dir	ected to	second so to be post W. Liber	State and the state of
Signed_		Date	Phone:	



"Historic Resources of Victoria"
Multiple Resource Nomination
Victoria, Victoria County, Texas
Site I-223
103-105 W. Santa Rosa
Photographer: Daniel Hardy, 1984
Negative filed with Texas Historical Commission
Camera facing Southwest
Photo
77 of 110

# Please refer to the map in the Multiple Property Cover Sheet for this property

Multiple Property Cover Sheet Reference Number: 64000855