United States Department of the InteriorNational Park Service

National Register of Historic Places Inventory—Nomination Form

For NPS use	only		
received	AUG	11	198
date entere	d	0	100

Continuation sheet

Item number all

Page 51

Historic Sites Inventory	6.USGS Quad No. <u>2897-441</u> Site No. <u>I-750</u>
(Adapted from THC HSI Form, 10-83)	7.UTM Sector No. 694-3186
1. E. H. D. Bendt House	8. Date: Factual Est 1926
2. 407 S. DeLeon	9. Architect/Builder N/A
3.Owner Lois Bendt	Contractor
4.Address same, 77901	
5.Legal Description OTS Blk 155 S. ½ Lot 1	11.Present Use residential
Description: 12: Type dwelling; bungalow	13. No. stories 1 1/2
14.Const. Materials wood frame w/ weatherb	oard siding & wood shingle roof
15. Plan_	16.Roof typegable
17.Roof/cornice details exposed rafters &	beams under wide eaves
	elev.
	ights, paired & grouped
20.Entrances single entry centered on E.	
21.Porches 3-bay shed porch across E. ele	
	lude bungalow details; massive brick columns
supporting elongated elliptical arch; bric	k balustrade and brick half-piers marking
entry bay; stick-detailed gabled dormer ce	entered on symmetrcal E. elev.; fixed, 4-light
windows on E. elev.	*
23. Interior details	
24. Associated outbldgs./structures weather	rboard, gable roofed carraige house/shed at
25.Present condition	
26. Significance good: ARCHITECTURE. An	excellent example of bungalow architecture in
26.Significance good: ARCHITECTURE. An Victoria. It was built for E.H.D. Bendt,	excellent example of bungalow architecture in
26.Significance good: ARCHITECTURE. An	excellent example of bungalow architecture in
26.Significance good: ARCHITECTURE. An	excellent example of bungalow architecture in
26.Significance good: ARCHITECTURE. An	excellent example of bungalow architecture in
26.Significance good: ARCHITECTURE. An	excellent example of bungalow architecture in
26.Significance good: ARCHITECTURE. An Victoria. It was built for E.H.D. Bendt,	excellent example of bungalow architecture in a clerk with Anchor Lumber Co.
26.Significance good: ARCHITECTURE. An Victoria. It was built for E.H.D. Bendt, 27.Context: MovedDateor origin	excellent example of bungalow architecture in a clerk with Anchor Lumber Co. nal site 28.Area description residential
26.Significance good: ARCHITECTURE. An Victoria. It was built for E.H.D. Bendt, 27.Context: Moved Date or original area in S.E. quadrant of the original town	excellent example of bungalow architecture in a clerk with Anchor Lumber Co. nal site 28.Area description residential
26. Significance good: ARCHITECTURE. An Victoria. It was built for E.H.D. Bendt, 27. Context: Moved Date or origin area in S.E. quadrant of the original town 29. Bibliography County tax rolls: City	excellent example of bungalow architecture in a clerk with Anchor Lumber Co. nal site 28. Area description residential site 34. YEAR DRWR ROLL FRME ROLL FRME THC 12
26. Significance good: ARCHITECTURE. An Victoria. It was built for E.H.D. Bendt, 27. Context: Moved Date or origin area in S.E. quadrant of the original town 29. Bibliography County tax rolls: City directories	excellent example of bungalow architecture in a clerk with Anchor Lumber Co. nal site 28.Area description residential site 34. YEAR DRWR ROLL FRME ROLL FRME
26. Significance good: ARCHITECTURE. An Victoria. It was built for E.H.D. Bendt, 27. Context: Moved Date or origin area in S.E. quadrant of the original town 29. Bibliography County tax rolls: City	excellent example of bungalow architecture in a clerk with Anchor Lumber Co. nal sitex 28. Area descriptionresidentialnsite 34. YEAR DRWR ROLL FRME
26. Significance good: ARCHITECTURE. An Victoria. It was built for E.H.D. Bendt, 27. Context: Moved Date or origin area in S.E. quadrant of the original town 29. Bibliography County tax rolls: City directories 30. Informant(s)	nal site 28. Area description residential nsite 34. YEAR DRWR ROLL FRME THC 12 7 to to to Photos: 35. Slides Photos: 35. Slides 28. Area description residential to
26. Significance good: ARCHITECTURE. An Victoria. It was built for E.H.D. Bendt, 27. Context: Moved Date or origin area in S.E. quadrant of the original town 29. Bibliography County tax rolls: City	nal site 28. Area description residential nsite 34. YEAR DRWR ROLL FRME THC 12 7 to to to Photos: 35. Slides 36.35mm B & W 1-64:1A-5A
26. Significance good: ARCHITECTURE. An Victoria. It was built for E.H.D. Bendt, 27. Context: Moved Date or origin area in S.E. quadrant of the original town 29. Bibliography County tax rolls: City directories 30. Informant(s) 31. Designations: HABS (no.)TEX- RTHL; File name	nal site 28. Area description residential site 34. YEAR DRWR ROLL FRME THC 12
26. Significance good: ARCHITECTURE. An Victoria. It was built for E.H.D. Bendt, 27. Context: Moved Date or origin area in S.E. quadrant of the original town 29. Bibliography County tax rolls: City directories 30. Informant(s) 31. Designations: HABS (no.)TEX	nal site 28. Area descriptionresidential site 34. YEAR DRWR ROLL FRME THC 12

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE


NATIONAL REGISTER OF HISTORIC PLACES EVALUATION/RETURN SHEET

	Iouse (Victoria MRA)				
Victoria County TEXAS					AUG 1986
TEXAS				Working No	
				Fed. Reg. Date:	9/11/06 -9/25/86 CCEPT 9-22-86
				Action:	CEPT CEPT
resubmission				ActionA	TIIRN 9-22-86
	n or local government			RE	JECT
owner objection					
☐ appeal					
Substantive Review:	sample	equest	appeal	□ NR dec	dision
Reviewer's comments:					
				see continua	
	V				
Nomination returned for	technical correction substantive reasons		v		
1. Name					
2. Location					
3. Classification					
	Ownership		Status	Present Us	
Category	Public Acquisition		Accessible	Fresent Os	96
4. Owner of Property				d Brancher	the case of appropriately
5. Location of Legal Des	cription		1998		
6. Representation in Exi	sting Surveys	Alexander of		The second of	To the territory of the contract of the
Has this property been de	termined eligible?	yes 🗆 r	no		
7. Description					
Condition		Check or	10	Check one	
excellent	deteriorated	unalt	ered	origin	al site
good	ruins	alter	ed	☐ moved	d date
fair	unexposed				
Describe the present and	original (if known) physical	l appearance			
summary paragraph					
completeness					
☐ clarity ☐ alterations/integrity					
dates					
boundary selection					

8. Significance	
Period Areas of Significance—Check and justify below	
Specific dates Builder/Architect Statement of Significance (in one paragraph)	
summary paragraph completeness clarity applicable criteria justification of areas checked relating significance to the resource context relationship of integrity to significance justification of exception other	Pault, E. M. D. Hause (Viotoria MRA) Viotoria County On Total On
9. Major Bibliographical References	
Acreage of nominated property Ouadrangle name UTM References	
Verbal boundary description and justification	
11. Form Prepared By	Tomasa State Commission
12. State Historic Preservation Officer Certification The evaluated significance of this property within the state is:	
nationalstatelocal State Historic Preservation Officer signature title date	
13. Other Maps Photographs Other	
Questions concerning this nomination may be directed to	in the first property that the second of the second
Signed Doger Date 9/21/8	Phone:

United States Department of the Interior National Park Service

National Register of Historic Places Inventory—Nomination Form



Continuation sheet

Item number

Page

Multiple Resource Area Thematic Group dnr-11

Nan		XAS	Corre	latives Andres 9/22/41
Non	ningtion/Type of Poview	Substantive Review	Cours	100
NOI	nination/Type of Review			Date/Signature
1.	Alden, C.R., Building	Substantive Review	Keeper	William D. Busho
		1	Attest	Bruce J. noble a. 12/8
2.	Alonso, Frank, House	Substantive Nevie	Keeper	William B. Bushon
		0	Attest	Bruce g. noble, Jr. 12/8/
. 3.	Barden0'Conner House	Entered in the National Register	Keeper	Helous Byen 149,
			Attest	Bruce g. noble p. 12/8/
4.	Barnes, W.C., House	Substative Keyley	Keeper	William B. Bushon
			Attest	Bruce J: Noble, p. 12/8/8
5.	Bendt, E.H.D., House	Entered in the Mational Register	Keeper	Shelmer Byen 12/9
			Attest	Bruce J. Moble D. 12/8/8
6.	Bettin, Max, House	Substitutive forigh	Keeper	Wilhan B. Busto
			Attest	
7.	B'Nai Isreal	Entered in the	Keeper	Delvery Byen 12/9,
			Attest	
8.	Braman House	Substantive Review	Keeper	William B. Bushon
		0	Attest	Bruce J. noble, p. 12/
9.	Buhler, Theodore, House	Sabata to An	Keeper	William B. Bushing
		U	Attest	Druce g. noble p. 12/8/
10.	Buhler, F.S., House	Substantive Leader	Keeper	William B. Bushay
	10E/C-N-R	GESTERSION O	Attest	Bruce J. noble, p. 12/8/

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES EVALUATION/RETURN SHEET

Bendt, E. H. D., House (Victoria MRA)	
Victoria County	al. las
TEXAS	Working No. 8/11/86
	Fed. Reg. Date: 2/2/88
	Date Due: /2/19/86
resubmission nomination by person or local government	Action:ACCEPT /2 -9-86
▼ resubmission	RETURN
nomination by person or local government	REJECT
owner objection	Federal Agency:
□ appeal	
2000 (1900 - 1900 - 1900 - 1900 <u>- 19</u> 00 (1900 - 1900 - 1900 - 1900 (1900 - 1900 -	
Substantive Review: sample request appeal	☐ NR decision
Reviewer's comments:	
Herievel's comments.	
	a min Acout - C.
Technical corrections completed.	Recom./Criteria Accept - C Reviewer Noble
	Reviewer // voice
	Discipline Historian
	Date 12/8/86
	see continuation sheet
Nomination returned for:technical corrections cited below	
substantive reasons discussed below	
1. Name	The Department of the state of the second of
2.1	
2. Location	
3. Classification	
Category Ownership Status	Present Use
	Present Use
Category Ownership Status Public Acquisition Accessible	Present Use
Category Ownership Status	Present Use
Category Ownership Status Public Acquisition Accessible 4. Owner of Property	Present Use
Category Ownership Status Public Acquisition Accessible	Present Use
Category Ownership Public Acquisition Status Accessible 4. Owner of Property 5. Location of Legal Description	Present Use
Category Ownership Status Public Acquisition Accessible 4. Owner of Property	Present Use
Category Ownership Public Acquisition Status Accessible 4. Owner of Property 5. Location of Legal Description	Present Use
Category Ownership Public Acquisition Status Accessible 4. Owner of Property 5. Location of Legal Description 6. Representation in Existing Surveys Has this property been determined eligible?	Present Use
Category Ownership Public Acquisition Status Accessible 4. Owner of Property 5. Location of Legal Description 6. Representation in Existing Surveys	Present Use
Category Ownership Public Acquisition Status Accessible 4. Owner of Property 5. Location of Legal Description 6. Representation in Existing Surveys Has this property been determined eligible? yes no 7. Description	
Category Ownership Public Acquisition 4. Owner of Property 5. Location of Legal Description 6. Representation in Existing Surveys Has this property been determined eligible?	Check one
Category Ownership Public Acquisition Status Accessible 4. Owner of Property 5. Location of Legal Description 6. Representation in Existing Surveys Has this property been determined eligible?	
Category Ownership Public Acquisition 4. Owner of Property 5. Location of Legal Description 6. Representation in Existing Surveys Has this property been determined eligible?	Check one
Category Ownership Public Acquisition 4. Owner of Property 5. Location of Legal Description 6. Representation in Existing Surveys Has this property been determined eligible?	Check one Original site
Category Ownership Public Acquisition 4. Owner of Property 5. Location of Legal Description 6. Representation in Existing Surveys Has this property been determined eligible?	Check one Original site
Category Ownership Public Acquisition 4. Owner of Property 5. Location of Legal Description 6. Representation in Existing Surveys Has this property been determined eligible? yes no 7. Description Condition excellent deteriorated unaltered altered altered altered altered	Check one Original site
Category Ownership Public Acquisition 4. Owner of Property 5. Location of Legal Description 6. Representation in Existing Surveys Has this property been determined eligible?	Check one Original site
Category Ownership Public Acquisition 4. Owner of Property 5. Location of Legal Description 6. Representation in Existing Surveys Has this property been determined eligible?	Check one Original site
Category Ownership Public Acquisition 4. Owner of Property 5. Location of Legal Description 6. Representation in Existing Surveys Has this property been determined eligible? yes no 7. Description Condition excellent good ruins fair Describe the present and original (if known) physical appearance	Check one Original site
Category Ownership Public Acquisition 4. Owner of Property 5. Location of Legal Description 6. Representation in Existing Surveys Has this property been determined eligible? yes no 7. Description Condition Check one unaltered unaltered good ruins altered altered good ruins altered Describe the present and original (if known) physical appearance	Check one Original site
Category Ownership Public Acquisition Accessible 4. Owner of Property 5. Location of Legal Description 6. Representation in Existing Surveys Has this property been determined eligible?	Check one Original site
Category Ownership Public Acquisition Accessible 4. Owner of Property 5. Location of Legal Description 6. Representation in Existing Surveys Has this property been determined eligible? yes no 7. Description Condition excellent good ruins deteriorated good ruins daltered fair Describe the present and original (if known) physical appearance summary paragraph completeness clarity alterations/integrity	Check one Original site
Category Ownership Public Acquisition Accessible 4. Owner of Property 5. Location of Legal Description 6. Representation in Existing Surveys Has this property been determined eligible? yes no 7. Description Condition C	Check one Original site
Category Ownership Public Acquisition Accessible 4. Owner of Property 5. Location of Legal Description 6. Representation in Existing Surveys Has this property been determined eligible? yes no 7. Description Condition excellent good ruins deteriorated good ruins daltered fair Describe the present and original (if known) physical appearance summary paragraph completeness clarity alterations/integrity	Check one Original site

8. Signific	icance			
Period	Areas of Significance—Check and justify be	elow		
Specific d	dates Builder/Architect nt of Significance (in one paragraph)			
compl clarity applic justific relatin relatio	cable criteria cable criteria cation of areas checked ng significance to the resource ext conship of integrity to significance cication of exception		right of the control	
9. Major	r Bibliographical References			
10. Geog	graphical Data	417		
	of nominated property gle name ferences			
Verbal bo	oundary description and justification			This is a state of the state of
11. Form	m Prepared By		and the second of the second o	in the same
	te Historic Preservation Officer Certification uated significance of this property within the	state is:		Accepted the service of
	nationalstatel	local		
State His	storic Preservation Officer signature			
title	date			
13. Othe	er			
☐ Maps ☐ Photo ☐ Other	ographs	The state of the s	Total Company	
Question	ns concerning this nomination may be directed	I to Bruce	Noble (202) 343 - 9547	to a ninetip an accided.
Signed_		Date	Phone:	



"Historic Resources of Victoria"
Multiple Resource Nomination
Victoria, Victoria County, Texas
Site I-750
407 S. DeLeon
E.H.D. Bendt House
Photographer: Daniel Hardy, 1984
Negative on file with Texas Historical Commission
Camera facing Southwest
Photo

30 of 110

Please refer to the map in the Multiple Property Cover Sheet for this property

Multiple Property Cover Sheet Reference Number: 64000855