NPS Form 10-900-a		OMB	768 NO. 1024	-0018	
(3-82)		Expire	es 10-	31-87	
United States Department of the Interior National Park Service	For	For NPS use only			
National Register of Historic Places	rec	eived SEP	16	1088	
Inventory-Nomination Form		e entered	10	1000	
inventory-nonination Form					
Continuation sheet Cuero, Texas M-R Nomination Item number all		Page	22		
				1.1.1.	
		den la			
TEXAS HISTORIC SITES INVENTORY FORM - TEXAS HISTORICA					
DEWITT DEW 5. USGS Quad No. 2997 City/Rural CUERD CU UTM Sector 667-321	-121	Site N	0. 3	51	
City/Rural CUERO CU UTM Sector 667-321 2. Name HOUSE AT 6. Date: Factual	. /	Ect	188	0	
Address 609 E LIVE DAK 7. Architect/Builder Unk	nown	ESI			
	Contractor			1	
3. Owner James L.". Prause 8. Style/Type L-plan	dwelling	Ser		-	
	iential	-			
Address 609 E. Live Dak Cuero TX 77954 9. Original Use resid	ential				
4. Block/Lot OTS/B1k 25/Lots 14 Present Use resid					
4. Block/Lot OTS/Blk 25/Lots 14 Present Use resid 10. Description 1 1/2-story frame dwelling w/ L plan; exterior w	alls w/ w			-	
4. Block/Lot OTS/Blk 25/Lots 14 Present Use resid 10. Description 1 1/2-story frame dwelling w/ L plan; exterior w siding; gable roof w/ composition shingles; wood-sash	double-hu	ng window	15		
4. Block/Lot OTS/Blk 25/Lots 14 Present Use resid 10. Description 1 1/2-story frame dwelling w/ L plan; exterior w	alls w/ w double-hu and side	ng window lights; 3	s 5-bay		
4. Block/Lot OTS/Blk 25/Lots 14 Present Use resid 10. Description 1 1/2-story frame dwelling w/ L plan; exterior w siding; gable roof w/ composition shingles; wood-sash w/ 2/2 lights; single-door primary entrance w/ transom porch inset on N. elev.; box columns w/ molded caps; j 11. Present Condition good	walls w/ w double-hu and side iig-sawn bu	ng window lights; 3 rackets;	s 5-bay two		
 4. Block/Lot OTS/Blk 25/Lots 14 Present Use resid 10. Description 1 1/2-story frame dwelling w/ L plan; exterior w siding; gable roof w/ composition shingles; wood-sash w/ 2/2 lights; single-door primary entrance w/ transom porch inset on N. elev.; box columns w/ molded caps; j 11. Present Condition good 12. Significance ARCHITECTURE: Like its neighbor, 607 E. Live 	walls w/ w double-hu and side ig-sawn b Oak (Site	ng window lights; 3 rackets; No. 350)	s 5-bay two		
 4. Block/Lot OTS/Blk 25/Lots 14 Present Use resid 10. Description 1 1/2-story frame dwelling w/ L plan; exterior w siding; gable roof w/ composition shingles; wood-sash w/ 2/2 lights; single-door primary entrance w/ transom porch inset on N. elev.; box columns w/ molded caps; j 11. Present Condition good 12. Significance ARCHITECTURE: Like its neighbor, 607 E. Live this house was owned by John Muti until 1898 when A. R 	walls w/ w double-hu and side ig-sawn b Oak (Site Ratti is 1:	ng window lights; 3 rackets; No. 350) isted as	s 5-bay two , its		
 4. Block/Lot OTS/Blk 25/Lots 14 Present Use resid 10. Description 1 1/2-story frame dwelling w/ L plan; exterior w siding; gable roof w/ composition shingles; wood-sash w/ 2/2 lights; single-door primary entrance w/ transom porch inset on N. elev.; box columns w/ molded caps; j 11. Present Condition good 12. Significance ARCHITECTURE: Like its neighbor, 607 E. Live this house was owned by John Muti until 1898 when A. R owner in county tax rolls. It is one of Cuero's earli 	walls w/ w double-hun and side ig-sawn br Oak (Site Ratti is 1 est and mo	ng window lights; 3 rackets; No. 350) isted as ost outst	s 5-bay two , its andia	ng	
 4. Block/Lot OTS/Blk 25/Lots 14 Present Use resid 10. Description 1 1/2-story frame dwelling w/ L plan; exterior w siding; gable roof w/ composition shingles; wood-sash w/ 2/2 lights; single-door primary entrance w/ transom porch inset on N. elev.; box columns w/ molded caps; j 11. Present Condition good 12. Significance ARCHITECTURE: Like its neighbor, 607 E. Live this house was owned by John Muti until 1898 when A. R owner in county tax rolls. It is one of Cuero's earli 13. Relationship to Site: Moved ? Date ca. 1880 or Original Site (descr 	walls w/ w double-hun and side ig-sawn br Oak (Site Ratti is 1: est and mo ribe) in a f	ng window lights; 3 rackets; No. 350) isted as ost outst	s 5-bay two , its andia	ng	
 4. Block/Lot OTS/Blk 25/Lots 14 Present Use resid 10. Description 1 1/2-story frame dwelling w/ L plan; exterior w siding; gable roof w/ composition shingles; wood-sash w/ 2/2 lights; single-door primary entrance w/ transom porch inset on N. elev.; box columns w/ molded caps; j 11. Present Condition good 12. Significance ARCHITECTURE: Like its neighbor, 607 E. Live this house was owned by John Muti until 1898 when A. R owner in county tax rolls. It is one of Cuero's earli 13. Relationship to Site: Moved ? Date ca. 1880 or Original Site (descr east of the CBD; in the middle of the south side of th 	walls w/ w double-hun and side ig-sawn br Oak (Site Ratti is 1: est and mo ribe) in a f	ng window lights; 3 rackets; No. 350) isted as ost outst	s 5-bay two , its andia	ng	
 4. Block/Lot OTS/Blk 25/Lots 14 Present Use resid 10. Description 1 1/2-story frame dwelling w/ L plan; exterior w siding; gable roof w/ composition shingles; wood-sash w/ 2/2 lights; single-door primary entrance w/ transom porch inset on N. elev.; box columns w/ molded caps; j 11. Present Condition good 12. Significance ARCHITECTURE: Like its neighbor, 607 E. Live this house was owned by John Muti until 1898 when A. R owner in county tax rolls. It is one of Cuero's earli 13. Relationship to Site: Moved ? Date ca. 1880 or Original Site (descr east of the CBD; in the middle of the south side of th 14. Bibliography Tax Rolls, Sanborn Maps 15. Informant 	walls w/ w double-hun and side ig-sawn br Oak (Site Ratti is 1: est and mo ribe) in a f	ng window lights; 3 rackets; No. 350) isted as ost outst residenti	s 5-bay two its andin al an	ng	
 4. Block/Lot <u>OTS/Blk 25/Lots 14</u> Present Use <u>resid</u> 10. Description <u>1 1/2-story frame dwelling w/ L plan; exterior w</u> siding; gable roof w/ composition shingles; wood-sash w/ 2/2 lights; single-door primary entrance w/ transom porch inset on N. elev.; box columns w/ molded caps; j 11. Present Condition <u>good</u> 12. Significance <u>ARCHITECTURE: Like its neighbor, 607 E. Live</u> this house was owned by John Muti until 1898 when A. R owner in county tax rolls. It is one of Cuero's earli 13. Relationship to Site: Moved ? Date <u>ca. 1880</u> or Original Site (descr <u>east of the CBD; in the middle of the south side of th</u> 14. Bibliography <u>Tax Rolls, Sanborn Maps</u> 15. Informant 	walls w/ w double-hun and side iig-sawn br Oak (Site Ratti is 1: est and mo ribe) <u>in a</u> he block.	ng window lights; 3 rackets; No. 350) isted as ost outst residenti Date .	s 5-bay two its andin al an	ng rea	
 4. Block/Lot OTS/Blk 25/Lots 14 Present Use resid 10. Description 1 1/2-story frame dwelling w/ L plan; exterior w siding; gable roof w/ composition shingles; wood-sash w/ 2/2 lights; single-door primary entrance w/ transom porch inset on N. elev.; box columns w/ molded caps; j 11. Present Condition good 12. Significance ARCHITECTURE: Like its neighbor, 607 E. Live this house was owned by John Muti until 1898 when A. R owner in county tax rolls. It is one of Cuero's earli 13. Relationship to Site: Moved ? Date ca. 1880 or Original Site (descr east of the CBD; in the middle of the south side of th 14. Bibliography Tax Rolls, Sanborn Maps 15. Informant DESIGNATIONS 	walls w/ w double-hun and side iig-sawn br Oak (Site Ratti is 1) est and mo ribe) <u>in a</u> he block.	ng window lights; 3 rackets; No. 350) isted as ost outst residenti Date . ATA	s 5-bay two its andir al an July	ng rea	
4. Block/Lot OTS/Blk 25/Lots 14 Present Use resid 10. Description 1 1/2-story frame dwelling w/ L plan; exterior w siding; gable roof w/ composition shingles; wood-sash w/ 2/2 lights; single-door primary entrance w/ transom porch inset on N. elev.; box columns w/ molded caps; j 11. Present Condition good 12. Significance ARCHITECTURE: Like its neighbor, 607 E. Live	walls w/ w double-hun and side iig-sawn br Oak (Site Ratti is 1: est and mo ribe) <u>in a</u> he block.	ng window lights; 3 rackets; No. 350) isted as ost outst residenti Date .	s 5-bay two its andir al an July	ng rea	
4. Block/Lot OTS/Blk 25/Lots 14 Present Use resid 10. Description 1 1/2-story frame dwelling w/ L plan; exterior w siding; gable roof w/ composition shingles; wood-sash w/ 2/2 lights; single-door primary entrance w/ transom porch inset on N. elev.; box columns w/ molded caps; j 11. Present Condition good 12. Significance ARCHITECTURE: Like its neighbor, 607 E. Live this house was owned by John Muti until 1898 when A. R owner in county tax rolls. It is one of Cuero's earli 13. Relationship to Site: Moved ? Date ca. 1880 or Original Site (descr east of the CBD; in the middle of the south side of th 14. Bibliography Tax Rolls, Sanborn Maps 15. Informant 16. Recorder Hardy-H DESIGNATIONS NRIS No. Old THC Code B&W 4×5s RTHL HABS (no.) TEX 35mm Negs	walls w/ w double-hun and side iig-sawn br Oak (Site Ratti is 1: est and mo ribe) <u>in a</u> he block.	ng window lights; 3 rackets; No. 350) isted as ost outst residenti Date ATA Slides4	s 5-bay two its andir al an July	ng rea	
4. Block/Lot OTS/Blk 25/Lots 14 Present Use resid 10. Description 1 1/2-story frame dwelling w/ L plan; exterior w siding; gable roof w/ composition shingles; wood-sash w/ 2/2 lights; single-door primary entrance w/ transom porch inset on N. elev.; box columns w/ molded caps; j 11. Present Condition good 12. Significance ARCHITECTURE: Like its neighbor, 607 E. Live this house was owned by John Muti until 1898 when A. R owner in county tax rolls. It is one of Cuero's earli 13. Relationship to Site: Moved ? Date ca. 1880 or Original Site (descr east of the CBD; in the middle of the south side of th 14. Bibliography Tax Rolls, Sanborn Maps 15. Informant 15. Recorder Hardy-H DESIGNATIONS DESIGNATIONS NRIS No. Old THC Code B&W 4×5s IR: Individual Historic District 35mm Negs	walls w/ w double-hun and side iig-sawn br Oak (Site Ratti is 1) est and mo ribe) in a he block. Neck-Moore PHOTO D	ng window lights; 3 rackets; No. 350) isted as ost outst residenti Date ATA Slides4	s 5-bay two its andir al an July	ng rea y 1986	
4. Block/Lot OTS/Blk 25/Lots 14 Present Use resid 10. Description 1 1/2-story frame dwelling w/ L plan; exterior w siding; gable roof w/ composition shingles; wood-sash w/ 2/2 lights; single-door primary entrance w/ transom porch inset on N. elev.; box columns w/ molded caps; j 11. Present Condition _good 12. Significance ARCHITECTURE: Like its neighbor, 607 E. Live	walls w/ w double-hun and side iig-sawn br Oak (Site Ratti is 1: est and mo ribe) <u>in a</u> be block. Heck-Moore PHOTO D/ ROLL FRMM	ng window lights; 3 rackets; No. 350) isted as ost outst residenti Date ATA Slides E to [s 5-bay two its andir al an July	ng rea y 1986	
4. Block/Lot OTS/Blk 25/Lots 14 Present Useresid 10. Description _1 1/2-story frame dwelling w/ L plan; exterior w siding; gable roof w/ composition shingles; wood-sash w/ 2/2 lights; single-door primary entrance w/ transom porch inset on N. elev.; box columns w/ molded caps; j 11. Present Conditiongood 12. SignificanceARCHITECTURE: Like its neighbor, 607 E. Live this house was owned by John Muti until 1898 when A. R owner in county tax rolls. It is one of Cuero's earli 13. Relationship to Site: Moved ? Dateca. 1880or Original Site (descr east of the CBD; in the middle of the south side of th 14. BibliographyTax Rolls, Sanborn Maps15. Informant	walls w/ w double-hun and side iig-sawn br Oak (Site Catti is 1: est and more ribe) in a ine block. leck-Moore PHOTO D ROLL FRMME 29 21	ng window lights; 3 rackets; No. 350) isted as ost outst residenti Date ATA Slides E to [s S-bay two its andir al ar July ROLL	ng rea y 1986 FRME	
4. Block/Lot OTS/Blk 25/Lots 14 Present Use resid 10. Description 1 1/2-story frame dwelling w/ L plan; exterior w siding; gable roof w/ composition shingles; wood-sash w/ 2/2 lights; single-door primary entrance w/ transom porch inset on N. elev.; box columns w/ molded caps; j 11. Present Condition good 12. Significance ARCHITECTURE: Like its neighbor, 607 E. Live this house was owned by John Muti until 1898 when A. R owner in county tax rolls. It is one of Cuero's earli 13. Relationship to Site: Moved ? Date ca. 1880 or Original Site (descr east of the CBD; in the middle of the south side of th 14. Bibliography Tax Rolls, Sanborn Maps 15. Informant 16. Recorder Hardy-H DESIGNATIONS TNRIS No. Old THC Code B&W 4×5s RTHL HABS (no.) TEX 35mm Negs NR: Individual Historic District YEAR DRWR Thematic Multiple-Resource Images	walls w/ w double-hun and side iig-sawn br Oak (Site Catti is 1: est and more ribe) in a ine block. leck-Moore PHOTO D ROLL FRMME 29 21	ng window lights; 3 rackets; No. 350) isted as ost outst residenti Date . ATA Slides 4 E to	s s-bay two its andir al an July ROLL 53	ng rea y 1986 FRME	
4. Block/Lot OTS/B1k 25/Lots 14 Present Use resid 10. Description 1 1/2-story frame dwelling w/ L plan; exterior w siding; gable roof w/ composition shingles; wood-sash w/ 2/2 lights; single-door primary entrance w/ transom	walls w/ w double-hun and side iig-sawn br Oak (Site Ratti is 1: est and mo ribe) in a be block. PHOTO D ROLL FRME 29 21 53 29	ng window lights; 3 rackets; No. 350) isted as ost outst residenti Date ATA Slides_4 to to to to No.	s S-bay two its and in al an July ROLL 53	rea y 1986 FRME 31	
4. Block/Lot OTS/Blk 25/Lots 14 Present Useresid 10. Description1 1/2-story frame dwelling w/ L plan; exterior w siding; gable roof w/ composition shingles; wood-sash w/ 2/2 lights; single-door primary entrance w/ transom porch inset on N. elev.; box columns w/ molded caps; j 11. Present Conditiongood 12. SignificanceARCHITECTURE: Like its neighbor, 607 E. Live this house was owned by John Muti until 1898 when A. R owner in county tax rolls. It is one of Cuero's earli 13. Relationship to Site: Moved ? Dateca. 1880or Original Site (descr east of the CBD; in the middle of the south side of th 14. BibliographyTax Rolls, Sanborn Maps15. Informant	walls w/ w double-hun and side iig-sawn br Oak (Site Ratti is 1: est and mo ribe) in a be block. PHOTO D ROLL FRME 29 21 53 29	ng window lights; 3 rackets; No. 350) isted as ost outst residenti Date ATA Slides_4 to to to to No.	s S-bay two its and in al an July ROLL 53	rea y 1986 FRME 31	
4. Block/Lot OTS/Blk 25/Lots 14 Present Use resid 10. Description 1 1/2-story frame dwelling w/ L plan; exterior w siding; gable roof w/ composition shingles; wood-sash w/ 2/2 lights; single-door primary entrance w/ transom	AL COMMISSI	ng window lights; 3 rackets; No. 350) isted as ost outst residenti Date ATA Slides_4 to to to to No.	s S-bay two its andir al an July ROLL 53 2	rea y 1986 FRME 31	
4. Block/Lot OTS/B1k 25/Lots 14 Present Use resid 10. Description 1 1/2-story frame dwelling w/ L plan; exterior w	Alls w/ wi double-hun and side iig-sawn br Oak (Site Ratti is 1: est and mo ribe) in a n e block. PHOTO D/ ROLL FRME 29 21 53 29 AL COMMISSI 7-121	ng window lights; 3 rackets; No. 350) isted as ost outst residenti Date Date ATA Slides 4 to to to to to No.	s S-bay two its andir al an July ROLL 53 2	rea y 1986 FRME 31 _ of _ 2	

United States Department of the Interior National Park Service

National Register of Historic Places **Continuation Sheet**

Section number _____ Page __

Multiple Resource Area Thematic Group Cuerto MRA Name DeWitt County, TEXAS State Nomination/Type of Review Date/Signature 21. Eicholz, William and L.F., House Entered in the Keeper National Register Attest Keeper/ 22. English-German School Substantive Review Attest Entered in the Reeper 23. Farris, J.B., House National Hegister Attest angel First Methodist Church Keeper Substantive Review Attest Entered in the Keeper C 4225. Friar, Alfred, House National Register Attest Anth Keeper (26. Frobese, William, Sr., House Substantive Review Attest Entered in the 27. Grace Episcopal Church Keeper/ Rational Sectates Attest 28. House at 1002 Stockdale Substantive Review Keeper Attest Keeper 29. House at 404 Stockdale Entered in the National Boginhar Attest Keeper and Al a 30. House at 609 East Live Oak

SUDELEVERTERNES TOATER

Attest

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES EVALUATION/RETURN SHEET

REQUESTED ACTION: NOMINATION

PROPERTY House at 609 East Live Oak NAME:

MULTIPLE Cuero MRA NAME:

STATE & COUNTY: TEXAS, De Witt

DATE RECEIVED: 9/16/88 DATE OF PENDING LIST: 9/27/88 DATE OF 16TH DAY: 10/13/88 DATE OF 45TH DAY: 10/31/88 DATE OF WEEKLY LIST:

REFERENCE NUMBER: 88001968

NOMINATOR: STATE

REASONS FOR REVIEW:

APPEAL:	N	DATA PROBLEM:	N	LANDSCAPE:	N	LESS THAN 50 YEARS:	N
OTHER:	N	PDIL:	N	PERIOD:	Ν	PROGRAM UNAPPROVED:	N
REQUEST:	N	SAMPLE:	Y	SLR DRAFT:	N		

COMMENT WAIVER: N

ACCEPT	RETURN	REJECT	10/31/88 DA	LE_
			/	-

ABSTRACT/SUMMARY COMMENTS:

Significant as one of Cuero's oldest and most outstanding L-plan dwellings.

RECOM./CRITERIA Accept-C	
REVIEWER Noble	
DISCIPLINE Historian	
DATE 10/31/88	

DOCUMENTATION see attached comments Y/N see attached SLR Y/N

CLASSIFICATION

count resource type

STATE/FEDERAL AGENCY CERTIFICATION

FUNCTION

historic current

DESCRIPTION

___architectural classification ___materials ___descriptive text

SIGNIFICANCE

Period Areas of Significance--Check and justify below

Specific dates Builder/Architect Statement of Significance (in one paragraph)

summary paragraph

- completeness
- clarity
- applicable criteria
- justification of areas checked
- relating significance to the resource
- context
- relationship of integrity to significance
- justification of exception
- other

BIBLIOGRAPHY	
GEOGRAPHICAL DATA	and a second second
verbal boundar UTMsboundary justi	
ACCOMPANYING DOCUMENTATION/PRESEN	TATION
sketch mapsUSGS maps	_photographspresentation
OTHER COMMENTS	
Questions concerning this nominat	ion may be directed to
	Phone
Signed	Date



"Historic Resources of Cuero, Texas" Multiple-Resource Nomination; city limits of Cuero, DeWitt County, Texas. Photo: David Moore of Hardy-Heck-Moore, Inc. 1986; negative with Texas Historical Commission, Austin, Texas. Subject: House, Site No. 351 609 E. Live Oak View: Camera looking southeast Photo 22 of 77

Please refer to the map in the Multiple Property Cover Sheet for this property

Multiple Property Cover Sheet Reference Number: 64000839